

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2024

Submitted Date:

07/26/2024

Document Number:

713601248**FIELD INSPECTION FORM**Loc ID 478057 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10758Name of Operator: OGRIS OPERATING LLCAddress: PO BOX 53467City: MIDLAND State: TX Zip: 79710**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	
WARD, GIENA		gward@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478058	TANK BATTERY	AC	09/17/2020		-	A.C. Tank Battery	RI

General Comment:This is a reclamation inspection of the A.C. Tank Battery.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	TRASH		
Comment:	There is trash and aerisol cans in the secondary containment that need to be dosposed.		
Corrective Action:	Comply with 606.		Date: 07/31/2024
Type	OTHER		
Comment:	There is inadequate netting covering the open top tank to prevent wildlife entry. There was a plastic tank with oily fluids and a secondary containment, which was full of oily fluids with no netting. There was also a bucket of oily fluids at the northeast side of the battery.		
Corrective Action:	Install or repair wildlife protection equipment. Comply with rule 902.b.		Date: 07/31/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Truck Loadout			
Comment:	There was stained soils observed in front of the west tank battery. There was oily fluid spilled over the secondary containment.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 08/26/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		There is eroison occurring at the access road and production facility which is transporting sediment onto the main road. The round rock has become displaced in areas and angular rock should be used for better outlet protection.				
Corrective Action:		Install or repair required BMPs per Rule 1002.f.(2)C				Date: 08/16/2024
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601249	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6640857