

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/26/2024

Submitted Date:

08/07/2024

Document Number:

716700014

FIELD INSPECTION FORM

 Loc ID 313117 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____
Operator Information:
 ECMC Operator Number: 10323
 Name of Operator: ENTEK GRB LLC
 Address: 165 SOUTH UNION #366
 City: LAKEWOOD State: CO Zip: 80228
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	
Roberts, James	970-620-6589	j75rober@blm.gov	
Murray, Richard		g.richard.murray@state.co.us	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258035	WELL	SI	05/01/2017	CBM	081-06994	FEDERAL 26-12-89 1 (OWP)	EI

General Comment:

On July 26, 2024 ECMC OWP staff members Richard Murray and Jim Hughes conducted a joint field inspection of the Entek Federal 26-12-89 #1. For the most recent field inspection report of this facility, please refer to Document #702502112. The purpose of this field inspection was to document current conditions at this location and secure the well as much as possible from potential tampering.

Location

Lease Road:			
Type	Access		
comment:	Gravel road.		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fencing around the perimeter of the location.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 258035 Type: WELL API Number: 081-06994 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Evaporation Lined: NO Pit ID: 268122 Lat: 40.971284 Long: -107.343947

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: No pit observed during this field inspection.

Corrective Action

Date:

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date:

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date:

ECMC Comments

Comment	User	Date
<p>On July 26, 2024 ECMC OWP staff members Richard Murray and Jim Hughes conducted a joint field inspection of the Entek Federal 26-12-89 #1. For the most recent field inspection report of this facility, please refer to Document #702502112. The purpose of this field inspection was to document current conditions at this location and secure the well as much as possible from potential tampering.</p> <p>Pit #268122 is registered to Cedar Ridge LLC and has an active status in the COGIS Database.</p> <p>The Bradenhead valve is exposed on the Federal 26-12-89 #1 well head. ECMC OWP locks were installed on each of the accessible valves. All valves were in the closed position at the conclusion of this field inspection.</p> <p>Four rig anchors were observed on this location. A barbed wire fence encloses the perimeter of this location. The stock panel gate was reattached with bailing wire.</p>	hughesjo	08/07/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716700015	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6655894