

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2024

Submitted Date:

09/12/2024

Document Number:

715500638

FIELD INSPECTION FORM

 Loc ID 313297 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____
Operator Information:
 ECMC Operator Number: 10673
 Name of Operator: GADECO LLC
 Address: 7535 EAST HAMPDEN AVE STE 400
 City: DENVER State: CO Zip: 80231
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Enforcement, ECMC		dnr_cogccenforcement@state.co.us	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Green, Trent	(303) 850-7490	trent@gfccap.com	
Neidel, Kris	(970) 846-5097	kris.neidel@state.co.os	
Engineering, ECMC		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285002	WELL	PR	05/01/2022	OW	081-07314	HIAWATHA STATE 2-36	PR

General Comment:[ECMC Inspection Report Summary](#)

On Tuesday, 09/10/2024, Inspector Kirby Burchett, conducted a follow up field inspection at Gadeco LLC on the Hiawatha State 2-36 well, Location #313297, in Moffat County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715500638 on 8/6/24. The following Corrective Actions are unresolved and original due dates remain:

- Spills
Refer to Inspection Photos for observed compliance issues.

While there during normal operations no additional compliance issue were observed.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location entrance		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	(303) 281-9948		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	
Crude Oil	Tank		
Comment:	Several spills in and around tank battery. Some appear to be covered with fresh soil instead of removal of all staining and impacted soil and disposed of accordingly as stated on previous corrective actions		
Corrective Action:	Remove and properly dispose of oily waste, all stained and impacted soils with disposal in an approved facility.		Date: 08/22/2024
Other			
Comment:	Compressor . Fresh gravel installed around unit with evidence of previous staining not properly handled.		
Corrective Action:	Remove and properly dispose of oily waste, all stained and impacted soils with disposal in an approved facility.		Date: 08/22/2024
Lube Oil	Pump Jack		
Comment:	Fresh soil around unit. Evidence of previous staining not properly handled.		
Corrective Action:	Remove and properly dispose of oily waste, all stained and impacted soils with disposal in an approved facility.		Date: 08/22/2024

In Containment: No

Comment: [Original inspection was a result of a BLM complaint and ECMC Compliance Inspector observed on 7/26/23 several areas of spills, staining and puddles of oily waste. Inspections on 9/26/23 and 2/21/24 observed the same issues. Location was finally cleaned up and passed inspection on 5/7/24. Routine inspection on 8/6/24 encountered the same issues as previous inspections. Operator representative stated "staining was a result of previous spills seeping up through new soil" which indicates spills were not properly handled even though representative stated "5-6 inches of soil was removed". A couple new spills were a result of tanks overfilled due to the evidence of oily waste down the sides of tanks.](#)

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Corral panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks in containment		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Methanol tank in earth containment at separator.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Lube oil tank in containment		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			

Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Venting:

Yes/No				
Comment:				
Corrective Action:				Date:

Flaring:

Type				
Comment:				

Corrective Action:	Date:
--------------------	-------

--

Inspected Facilities

Facility ID: 285002 Type: WELL API Number: 081-07314 Status: PR Insp. Status: PR

Producing Well

Comment: [June 2024 Production Report](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Ditches				
Ditches						
		Drains				

Comment: [Operator is responsible for maintaining Best Management Practices \(BMPs\) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403919733	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6704313
715500639	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6704310