

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2024

Submitted Date:

10/11/2024

Document Number:

712300072**FIELD INSPECTION FORM**Loc ID 487288 Inspector Name: Maxwell, Logan On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10805Name of Operator: FULCRUM ENERGY OPERATING LLCAddress: 240 SAINT PAUL STREET SUITE 502City: DENVER State: CO Zip: 80206**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		kris.neidel@state.co.us	
		scott.ramsey@state.co.us	
		chris.binschus@state.co.us	
		inspections@fulcrumeco.com	
		wes.corliss@fulcrumeco.com	
		alex.fischer@state.co.us	
		annalee@fulcrumef.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487288	LOCATION	AC	07/15/2024		-	Janet 0780 S5	CI

General Comment:

On 9/10/2024, Eastern Reclamation Work Lead Binschus and Reclamation Specialist Maxwell conducted a New Construction and Stormwater inspection in response to Form 42- Notice of Construction (Doc # 403861134) at Fulcrum Energy Operating's Janet 0780 S5 Oil and Gas Location in Jackson County, Colorado. Staff had a conversation with the Operator on site to discuss observations and compliance issues.

The following compliance issues were observed during this inspection:

- Stormwater BMPs
- OGD and 2A Conditions of Approval

Refer to the "Location," "Reclamation," and "Stormwater" sections of this inspection report for additional details.

Any new corrective actions without corrective action dates, requires that the Operator comply with the Rules as soon as possible or when environmental conditions permit. Location will remain out of compliance until corrective action(s) has (have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Pursuant to Rule 605.c, during drilling, the Operator will place directional signs at locations sufficient to advise emergency crews where drilling Operations are taking place.		
	At the time of inspection, the sign at the intersection of the public road and rig access road was observed to be missing information.		
Corrective Action:	Comply with Rule 605.c.	Date:	
Type	OTHER		
Comment:	Pursuant to Rule 406.c a copy of the approved Form 2A, and any Form 4 modifying the approved Form 2A, will be posted in a protected and conspicuous place on location upon commencement of operations with heavy equipment until the conclusion of interim Reclamation. It was observed in this inspection that the approved Form 2A, and any Form 4 modifying the approved Form 2A, has not been posted on the Location. Staff discussed this with the Operator and it was indicated that permit information was currently at another Location.		
Corrective Action:	Comply with Rule 406.c.	Date:	
Type	DRILLING/RECOMP		
Comment:	Pursuant to Rule 605.b, from the time of or prior to Move-In, Rig-Up, the Operator will place a sign or marker at the point of intersection of the public road and rig access road, and the sign will be maintained until the drill rig is released. The sign placed during drilling operations will identify the public road to be used in accessing the rig, along with all necessary emergency numbers, and will be posted in a conspicuous place at the drilling rig.		
	At the time of inspection, the sign at the intersection of the public road and rig access road was observed to be missing information.		
Corrective Action:	Comply with Rule 605.b.	Date:	
Type	OTHER		
Comment:	Pursuant to Rule 605.a, from the time of construction until Reclamation is complete, the Operator will post a sign at the entrance to an Oil and Gas Location.		
	At the time of this inspection, the sign was posted at the Location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-594-0477

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Location Construction

Location ID: 487288 CDP: _____

Comment: Pursuant to Form 2A #403211377, the size of Location's disturbance area is to be 6.61 acres. At the time of inspection, a disturbance of approximately 6.2 acres for the production and well pad area was mapped.

Corrective Action: _____ **Date:** _____

Form 2A COAs:**Comment:**

Corrective Action: _____ **Date:** _____

Wildlife BMPs:

Comment: Pursuant to Rule 1202.a.(8), the Operator is required to conduct pre-construction nesting migratory bird surveys between April 1- August 31. The Operator was out of compliance when Staff requested the survey and it was not provided. After discussions with the Operator, they communicated directly with CPW, who provided a 1202.a.(8) waiver on 9/6/2024, excluding them from this requirement.

Corrective Action: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
BERMS			

Comments: Erosion BMPs: At the time of inspection, stormwater BMPs have been installed (berms) around the entire perimeter during the construction phase of the location. A follow-up stormwater inspection will be conducted at a future date to ensure compliance with Rule 1002.f. standards. Refer to the ECMC Comments section for additional stormwater compliance information.

Other BMPs:

Corrective Action: _____ **Date:** _____

Comments: Erosion BMPs: Per Rule 1002.f., operators shall implement and maintain BMPs at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Operators shall implement BMPs in accordance with good engineering practices.

Other BMPs:

It was observed that round river rock was implemented at the stormwater outlet and in check dams in the perimeter ditch not per good engineering practices. Operator indicated that there was a geotextile fabric lining underneath, however Staff did not confirm. A follow up inspections will be conducted at a future date for compliance with Rule 1002.f.

Corrective Action: _____ **Date:** _____

Vehicle Tracking

Comments: Erosion BMPs: Pursuant to Form 2A COAs, and Operator's SWMP, BMPs, including vehicle tracking controls, were to be installed on the access road for entrance/exit to the pad (shared with Ray Ranch North Location).

Other BMPs: It was observed in this inspection that vehicle tracking control measures, such as a vehicle track pad, have not been installed; BMPs to minimize off-site sediment transport are missing or insufficient. See photo documentation from Inspection #712300071.

Corrective Action: Comply with Rule 1002.f. and Form 2A COAs

Date:

Comments: Erosion BMPs: Operator on site stated that a "Street Sweeper" has been employed to clean sediment tracked off-site and onto the public road. Street Sweeper was not observed on Location at time of inspection.

Other BMPs:

Corrective Action:

Date:

Comment:

Corrective Action:

Date:

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	<u>487288</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>CI</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental					
Waste Management:					
Type	Management	Condition	GPS (Lat) (Long)		
Comment	Pursuant to Form 2A #403211377 drilling fluids and cuttings will be disposed offsite.				
Corrective Action					Date:
Spill/Remediation:					
Comment:					
Corrective Action:					Date: _____
Emission Control Burner (ECB): _____					
Comment:					
Pilot: _____	Wildlife Protection Devices (fired vessels): _____				

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION Pass

Comment _____

At time of inspection, topsoil salvage operations appear to have been completed on the Location, however there are areas of the Location where it does not appear as though all topsoil had been salvaged or areas where topsoil had been utilized for other purposes pursuant to Rule 1002.b.

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS Fail

Comment _____

At the time of this inspection, it was observed that topsoil was temporarily tracked. No other BMPs have been implement in conjunction with tracking to minimize erosion, degradation and sediment transport per good engineering practices.

It was also observed that topsoil materials were utilized in the sediment trap. Utilization of topsoil material as part of stormwater controls does not comport with Rule 1002.c, as this places the topsoil resource at risk to degradation, contamination (commingling with sediment), and loss of the resource.

No perimeter stormwater BMPs had been installed around topsoil stockpile.

Staff was informed that some topsoil was removed by the Surface Owner and that they plan to seed the topsoil pile this fall.

Corrective Action _____

Comply with Rule 1002.f.(2). and 1002.c. to implement topsoil stormwater BMPs. All stockpiled soils shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production.

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Fail					

Comment:

Per Rule 1002.f., oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Pursuant to Form 2A COAs, and Operator's SWMP, BMPs, inlet and outlet protection was to be implemented for two culverts under access road and one culvert extending outside of disturbance area.

At the time of inspection, no inlet/outlet protection was implemented per good engineering practices. See photos 9 and 10.

Corrective Action:

Comply with Rule 1002.f. and Form 2A COAs

Date:

Pits:

NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403955002	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743411
712300082	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6743401