

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2024

Submitted Date:

11/01/2024

Document Number:

699700436

FIELD INSPECTION FORMLoc ID 323887 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Cholas, Nick		nick.cholas@state.co.us	
Toews, Wesley J	9703195683	wtoews@blm.gov	BLM West Slope
Longworth, Mike		mike.longworth@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Bankert, Wayne		wbankert@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
469498	Produced Water Transfer System	AC	08/24/2021		-	Cascade Creek Water Transfer System	EI

General Comment:

ECMC Environmental Inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities									
Facility ID:	469498	Type:	Produced	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 35

Comment: See Spill/Release ID 488230 for more information. Spill/Release occurred within High Priority Habitats (HPH) (Effective July 15, 2024). ECMC staff John Heil and Nick Cholas conducted an Environmental Inspection of the spill/release area and observed an excavation of Laramie's 4" produced water line that had failed. Potentially impacted fluids adjacent to the 4" produced water were observed within the excavation. Livestock fencing was present on the northwest side of the excavation but did not completely enclose the excavation. Multiple stockpiles of potentially impacted material were placed adjacent to the excavation. BMPs to prevent contamination of stormwater, surface water, Groundwater, and soil were absent at time of inspection.

Corrective Action: Operator shall comply with Rule 913.b.(5).i and fence or cover open excavations to prevent access when sites are not attended. Operator shall comply with Rule 913.b.(5).iv and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil. Operator shall comply with Rule 913.b.(5).v and incorporate Best Management Practices protective of the relevant wildlife species or habitat.

Date: _____

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water:

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403979673	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770120
699700437	20241017 Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770115