

State of Colorado  
Energy & Carbon Management Commission



Document Number:  
403994875

Date Received:  
11/14/2024

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Engineering

[dnr\\_cogccengineering@state.co.us](mailto:dnr_cogccengineering@state.co.us)

Toews, Wesley

[wtoews@blm.gov](mailto:wtoews@blm.gov)

TEP

[COGCCInspectionReports@terraep.com](mailto:COGCCInspectionReports@terraep.com)

Haverkamp, Curtis

[curtis.haverkamp@state.co.us](mailto:curtis.haverkamp@state.co.us)

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708904921

Inspection Date: 10/30/2024

FIR Submit Date: 10/30/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 335176

Location Name: FEDERAL-66S94W Number: 19NESE County: \_\_\_\_\_

Qtrqtr: NESE Sec: 19 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.509096 Longitude: -107.924075

#### FACILITY - API Number: 05-045-00 Facility ID: 335176

Facility Name: FEDERAL-66S94W Number: 19NESE

Qtrqtr: NESE Sec: 19 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.509096 Longitude: -107.924075

### CORRECTIVE ACTIONS:

1 CA# 200173

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 10/31/2024

Response: CA COMPLETED

Date of Completion: 10/31/2024

Storm water from well head was evacuated on 10/31/24. Vac-truck conducted hydro-excavation around well

Operator Comment: head. Very small leak on Larkin head fitting was discovered and was welded / repaired the same day. Repair job on Larkin head was tested and found to be successful. Excavation was backfilled, Corrective action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Storm water from well head was evacuated on 10/31/24. Vac-truck conducted hydro-excavation around well head. Very small leak on Larkin head fitting was discovered and was welded / repaired the same day. Repair job on Larkin head was tested and found to be successful. Excavation was backfilled, Corrective action #200173 complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 11/14/2024 11:57:35 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403994912	Source of well head leak at RMV 63-19. Repaired on 10/31/24.
-----------	--------------------------------------------------------------

Total Attach: 1 Files