

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2024

Submitted Date:

12/09/2024

Document Number:

709100460

FIELD INSPECTION FORM

Loc ID 475143 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Fritzler, Steve	(970) 867-9388	sfritzler@friesources.com	
Kyle Waggoner		kyle.waggoner@state.co.us	
Fritzler, Gene	(970) 768-0845	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475143	LOCATION	AC			-	FEHRINGER-612N52W 28SWNE	EI

General Comment:

This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	NFPA placard illegible on partially buried vessel next to pit (See Photo 25.)		
Corrective Action:	Install sign to comply 605.e.	Date:	03/04/2025

Emergency Contact Number:			
Comment:	Emergency Phone Number present on signage		
Corrective Action:		Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds observed within pit area / Comply with Rule 606		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	Large hoses, piping, fiberglass, wooden planks, metal equipment (shown in Photo 17) stored on location / Comply with Rule 606		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			
Crude Oil	Tank				
Comment:	Hydrocarbon stained soil observed adjacent to the pit area: (1) next to partially buried vessel, (2) on the partially buried vessel's sides and top, (3) and at the pipe's discharge point into the pit. It appears that E&P Waste was dumped into partially buried vessel's wildlife protection (wired netting) causing a buildup of E&P Waste. See photo documentation (Photos 19 - 21).				
Corrective Action:	Report spill or release of E&P waste via a Form 19 and contact ECMC EPS staff per Rule 912.b. Operator shall collect confirmation soil samples as described in the Rule 915.e.(2) Guidance Document. Operator will analyze soil samples for TPH (C6-C36), Table 915-1 Organic Compounds in Soil, Table 915-1 metals, and Table 915-1 Soil Suitability for Reclamation (Electrical conductivity, Sodium adsorption ratio, and pH by saturated paste method, boron (hot water soluble)).				Date: 12/09/2024
Crude Oil	Tank				
Comment:	Hydrocarbon stained soil observed within tank battery area.				
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free fluids and contact ECMC EPS staff per Rule 912.b.				Date: 12/09/2024
Crude Oil	Tank				
Comment:	Hydrocarbon stained soil observed next to vertical tank. See photo documentation (Photo 16)				
Corrective Action:	Report spill or release of E&P waste via a Form 19 and contact ECMC EPS staff per Rule 912.b. Operator shall collect confirmation soil samples as described in the Rule 915.e.(2) Guidance Document. Operator will analyze soil samples for TPH (C6-C36), Table 915-1 Organic Compounds in Soil, Table 915-1 metals, and Table 915-1 Soil Suitability for Reclamation (Electrical conductivity, Sodium adsorption ratio, and pH by saturated paste method, boron (hot water soluble)).				Date: 12/09/2024

In Containment: No

Comment: Operator shall submit the Produced Water Quality Analyses for the Fehringer #1 Pit (Facility ID 272486) via a Form 43, per Rule 909.j.

Previous Form 43 (Doc# 403643794) sampled the pit on Oct. 26, 2023. Per Rule 909.j.(2), "Operators will collect and analyze samples on an annual basis after the initial sampling and analysis."

☒ Multiple Spills and Releases?

Equipment:		corrective date
Type:	#	
Comment:	Multiple valves are not securly fastened. See photo documentation (Photos 6, 13, 15, 17, 21, and 24)	
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. If piping is no longer in use, unused equipment shall be removed from the facility. Either remove unused equipment (piping) and/or securely fasten each valve.	Date: 01/03/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	No wildlife protection equipment (e.g. netting) installed at partially buried tank at the pit area. (photo 23)				
Corrective Action:	Comply with Rule 902.b to install or repair wildlife protection equipment. The location will remain out of compliance until the corrective action has been resolved.				Date: 01/03/2025

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Multiple holes observed within bermed containment. See photo documentation.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 01/13/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

