

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
12/13/2024  
Submitted Date:  
12/19/2024  
Document Number:  
700300768

**FIELD INSPECTION FORM**

Loc ID 325310 Inspector Name: LABOWSKIE, STEVE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 31250  
Name of Operator: FRITZ & DIGMAN INC  
Address: PO BOX 70024  
City: ALBUQUERQUE State: NM Zip: 87197-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Digman, Rebecca	505-379-8689	rcdigman@yahoo.com	
Kosola, Jason		jason.kosola@state.co.us	
Flores, Marie		marie@walsheng.net	contactor for various operators in SW
Digman, Bernie	575-640-1867	berniekdigman@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214538	WELL	SI	06/01/2023	OW	067-06141	DAKOTA FEE 1	WK

**General Comment:**

Conduct spill response from previous days release. RIH with packerto 260', pressure to 460 psi, no leak on 4 1/2", RIH to 1260', no leak on 4 1/2". Only circulation is through perms shot on 12/12 at 1298'.  
Extent of spill area demonstrates secondary containment of fluids COA on Form 6 was not achived.  
Plugging operations continued with cracked casing flange leaking fluid and vacum truck used to remove from cellar while circulating.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	400 bbl rental tank not marked or contents labeled		
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	WELLHEAD	>= 5 bbls	
Comment:	While trying to establish circulation after perforating tubing at 1298' oil and produced water came to surface around wellhead through a cracked casing flange. Rig supervisor there was also a hose that came loose and contributed to the spill at wellhead and towards rig and equipment to the south. Vacuum truck and crews were responding to spill and removing free fluids when ECMC staff arrived. Operator filed Form 19 but has not submitted a Form 27 as required		
Corrective Action:	Submit Form 27 related to spill and clean-up/remediation. (Note: a Form 27 is also required for P&A)		Date: <u>01/15/2025</u>

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 214538 Type: WELL API Number: 067-06141 Status: SI Insp. Status: WK

**Cement**

Cement Contractor

Contractor Name: \_\_\_\_\_ Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): CR @ 1298' Cement Volume (sx): 147

Good Return During Job: \_\_\_\_\_ Cement Type: g

Comment: Stage tubing 4 1/2" and packer tubing in 7" casing, periodically pressuring up to test for casing leaks. Determine flow from previous day was circulation through perfs @ 1359'. Run tubing back in with cement retainer @ 1298', pump 30 bbls water to clean up, pump 147 sacks total through retainer. Shut down for weekend.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Workover**

Comment: Drake Well service rig and cementing equipment

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404035535	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834559">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834559</a>
700300772	spill and response	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834543">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834543</a>
700300773	vac truck cleaning up free fluids	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834544">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834544</a>
700300774	spill area	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834546">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6834546</a>