



<div>FORM</div> <div>6</div> <div>Rev 11/20</div>	<div>State of Colorado</div> <div>Energy & Carbon Management Commission</div> <div>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</div>		<div><div></div></div>		<div>DE</div> <div>ET</div> <div>OE</div> <div>ES</div>
	<div>Document Number:</div> <div>403950730</div> <div>Date Received:</div> <div>10/09/2024</div>				

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

ECMC Operator Number: 47120		Contact Name: Candice Barber	
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP		Phone: (307) 2334513	
Address: P O BOX 173779		Fax:	
City: DENVER	State: CO	Zip: 80217-	Email: candice_barber@oxy.com
For "Intent" 24 hour notice required,		Name: Tel:	
ECMC contact:		Email:	

Type of Well Abandonment Report: ☐ Notice of Intent to Abandon ☒ Subsequent Report of Abandonment

API Number 05-123-30567-00		Well Number: 21-4	
Well Name: ADAM FARM			
Location: QtrQtr: SWNE	Section: 4	Township: 2N	Range: 68W Meridian: 6
County: WELD		Federal, Indian or State Lease Number:	
Field Name: WATTENBERG		Field Number: 90750	

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.171306		Longitude: -105.004075	
GPS Data: GPS Quality Value: 1.4	Type of GPS Quality Value: PDOP	Date of Measurement: 09/27/2024	
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems			
<input type="checkbox"/> Other			
Casing to be pulled: <input type="checkbox"/> Yes <input type="checkbox"/> No		Estimated Depth:	
Fish in Hole: <input type="checkbox"/> Yes <input type="checkbox"/> No		If yes, explain details below	
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input type="checkbox"/> No		If yes, explain details below	
Details:			

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7435	7455	07/17/2024	RETAINER/SQUEEZED	7142
NIOBRARA	7172	7302	07/17/2024	RETAINER/SQUEEZED	7142
Total: 2 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	971	356	971	0	VISU
1ST	7+7/8	4+1/2	I-80	11.6	0	7620	864	7620	1080	CBL

Date Run: 1/23/2025 Doc [#403950730] Well Name: ADAM FARM 21-4

Page 1 of 3

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 300 with 100 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 7172 ft. with 100 sacks. Leave at least 100 ft. in casing 7142 CICR Depth
Perforate and squeeze at 4110 ft. with 100 sacks. Leave at least 100 ft. in casing 4080 CICR Depth
Perforate and squeeze at 1385 ft. with 100 sacks. Leave at least 100 ft. in casing 1355 CICR Depth
(Cast Iron Cement Retainer Depth)

Set 150 sacks half in. half out surface casing from 1135 ft. to 611 ft. Plug Tagged: ☒

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 1040 ft. of 4+1/2 inch casing Number of Days from Setting Surface Plug
Surface Plug Setting Date: 07/24/2024 Cut and Cap Date: 09/26/2024 to Capping or Sealing the Well: 64

*Wireline Contractor: AXIS *Cementing Contractor: RANGER

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☒ Yes ☐ No

Technical Detail/Comments:

CONTINUED PLUGGING PROCEDURE:

PERF AT 1165' WITH 100 SACKS OF CEMENT, CICR SET AT 1135' IN CASING

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Candice Barber

Title: REG ANALYST Date: 10/9/2024 Email: DJREGULATORY@OXY.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Jacobson, Eric Date: 1/23/2025

CONDITIONS OF APPROVAL, IF ANY LIST

COA Type **Description**

0 COA	
-------	--

ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
403950730	FORM 6 SUBSEQUENT SUBMITTED
403950743	OPERATIONS SUMMARY
403950757	CEMENT BOND LOG
403950761	OTHER
403950764	CEMENT JOB SUMMARY
403950766	OTHER
403950768	WELLBORE DIAGRAM
403950772	WIRELINER JOB SUMMARY

Total Attach: 8 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	2 months PA. Reviewed attachments. Pass.	01/22/2025

Total: 1 comment(s)