

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2025

Submitted Date:

04/01/2025

Document Number:

710500466

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Sanchez, Chris 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Serna, Abe		abe.serna@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
Longworth, Mike		mike.longworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427440	WATER GATHERING SYSTEM/LINE	AC	01/25/2012		-	Raton Basin Water Gathering 427440	EI
489660	SPILL OR RELEASE	AC			-	Longs Canyon Gathering Line Spill	EI

General Comment:

This is an Environmental Inspection for Spill Facility ID 489660, located in Las Animas County, Colorado.

Inspected Facilities									
Facility ID:	427440	Type:	WATER	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	489660	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spill/Remediation:**

Comment:

On 3/31/2025, ECMC conducted a Filed Inspection regarding Spill Facility ID # 489660 tied to Water Gathering Flowline, Facility ID 427440.

At the time of inspection, an ENR crew was onsite. There was an open excavation and the lines were exposed showing one area where repairs were made to a 4" steel water line.

From the spill source water flowed north-northwest to a culvert in the access road. The water then changed direction flowing east through the culvert into an area identified as State Waters. At the time of inspection, there was no indication the produced waters flowed into live State Waters in the Longs Canyon Creek.

The Operator shall provide additional spill details in the 10-day supplemental Form 19 identifying the distance between end of spill path and live waters.

The Operator shall coordinate with the ECMC Engineering Integrity Unit on the root cause and corrective actions for flowline repairs and pressure test the flowline in accordance with Rule 1102.j.

Corrective Action:

The Operator shall continue spill remediation in accordance with Rule 912.b

Date: 04/07/2025

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404148464	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6985611
710500467	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6985605