

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2025

Submitted Date:

04/03/2025

Document Number:

699700469

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Longworth, Mike		mike.longworth@state.co.us	
Cholas, Nick		nick.cholas@state.co.us	
Gardner, Mike		mgardner@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
464634	PRODUCED WATER TRANSFER SYSTEM	AC	09/27/2022		-	Silt Produced Water 464634	EI

General Comment:

ECMC Environmental Inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 464634 Type: PRODUCED API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: See Initial Form 19 Doc #404137774, Supplemental Form 19 Doc #404145198, Inspection Doc #699700463 and Inspection Doc #699700467 for more information. Spill/Release occurred within High Priority Habitats (HPH) (Effective July 15, 2024). ECMC staff John Heil conducted an Environmental Inspection of the spill/release point and the surrounding areas. The temporary polyline identified in Inspection Doc #699700467 was still present at time of inspection. The majority of the stock pond had been emptied by pumping fluids through the temporary polyline and the operator was utilizing vac trucks to remove the remaining fluids. A 12-inch PVC line was observed conveying water from the unnamed tributary to Dry Hollow Creek. INITIAL MITIGATION Doc #404145865 states "Additionally, a temporary 12-inch PVC line was attached to the discharge end of a culvert at the inlet to the pond and installed along the north side of the pond, diverting water within the unnamed drainage to flow into an earthen division ditch to Dry Hollow Creek." Water samples of the outflow of the 12-inch PVC indicate compliance with table 915-1 Organic and Inorganic Compounds in Groundwater (see Flume Outlet results on ANALYTICAL DATA SUMMARY TABLE(S) Doc #404145308.) Fluids and stained soils were still present on the west side of Co Rd 331 and stained soils were also present adjacent to the unnamed tributary of Dry Hollow Creek on the west side of Co Rd 331. See attached Photo Log for details.

Corrective Action: **Operator shall remove and dispose of all fluids and stained soils located on the west side of Co Rd 331. These include the soils adjacent the unnamed tributary of Dry Hollow Creek.**

Date: _____

Reportable: YES

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Lat

Long

Field Parameters:

Sample Location: _____

Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404152836	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6989897
699700470	20250325 Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6989883