

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2025

Submitted Date:

05/16/2025

Document Number:

694500771

FIELD INSPECTION FORMLoc ID 446527 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Penner, Annalee	417-773-2341	annalee.penner@fulcrumeo.com	
Fischer, Alex		alex.fischer@state.co.us	
Blohm, Justin	520-820-2380	justin.blohm@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
160027	UIC Disposal	AC	05/08/2020		-	Pintail 16	EI
446806	WELL	SI	05/01/2024	DSPW	057-06562	Pintail SWD 0780 1-16D	EI

General Comment:

On 5/16/25 ECMC staff, Kris Neidel inspected the Pintail Tank Battery. A spill of fluid to the tank battery was recently reported, doc #404206189. Corrective actions issued by ECMC in other inspections remain valid. Weather was 40 degrees and partly cloudy at the time of inspection. The following was observed: It was reported by Fulcrum Field staff that the water in the secondary containment was from recent storms, it was stated that all spilled fluid was removed after the spill. Debris was observed floating on stormwater in the containment area, It is believed that this is insulation from the tanks. It is believed that birds are attempting to tunnel into the spray foam insulation on the tanks and the insulation is becoming airborne and collecting in the containment. A bird was observed nested inside pipe insulation (on the east side of tank battery, see Photo #16 Some hydrocarbon staining was observed on piping inside tank battery (photo #14), Corrective Actions: prevent birds from tunneling into spray foam, remove foam debris from containment and prevent from becoming airborne (photo #14), remove hydrocarbon staining from inside tank battery, remove bird nest and prevent similar nesting. See attached photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris was observed floating on stormwater in the containment area, It is believed that this is insulation from the tanks. It is believed that birds are attempting to tunnel into the spray foam insulation on the tanks and the insulation is becoming airborne and collecting in the containment.		
Corrective Action:	prevent birds from tunneling into spray foam		Date: 09/01/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 446527 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: A bird was observed nested inside pipe insulation (on the east side of tank battery, see Photo #16)

Corrective Action: remove bird nest and prevent similar nesting.

Date: 05/23/2025

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	160027	Type:	UIC Disposal	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	446806	Type:	WELL	API Number:	057-06562	Status:	SI	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: Hydrocarbon staining was observed on piping inside tank battery (photo #14).

Corrective Action: Remove hydrocarbon staining from inside tank battery.

Date: 06/16/2025

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500772	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7054144