

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2025

Submitted Date:

07/31/2025

Document Number:

712300159

FIELD INSPECTION FORM

Loc ID: 324752 Inspector Name: Maxwell, Logan On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Findings:

- 12 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		annalee@fulcrumef.com	
		wes.corliss@fulcrumeo.com	
		inspections@fulcrumeo.com	
		aaron.trujillo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324752	LOCATION	AC			-	Veneta 0780 S32 CTB	RI

General Comment:

On 06/05/2025, Northwest Reclamation Specialist Maxwell, conducted an Interim Reclamation and Stormwater inspection at Fulcrum Energy Operating's Veneta 0780 S32 CTB Oil and Gas Location in Jackson County, Colorado.

The Location is located in the following HPH: Black Bear and 1202.d. Density habitats for Greater sage -grouse priority habitat management.

The following compliance issues were observed during this inspection:

- Wildlife Protections
- Good housekeeping
- Weed management
- Stained Soils
- Topsoil Protection

Refer to the Location and Reclamation sections of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	It was observed in this inspection that Undesirable plant species, such as Canada Thistle and Russian Thistle, have established along portions of the perimeter and on the Topsoil stockpile.		
Corrective Action:	Comply with Rule 606.c. and 1002.c.	Date:	08/07/2025
Type	OTHER		
Comment:	It was observed in this inspection that there are multiple containers located around the Location on the ground or that contain oily or potentially combustible waste.		
Corrective Action:	Comply with Rule 606.d.(3). and 610.j.	Date:	08/07/2025
Type	TRASH		
Comment:	It was observed in this inspection that various trash, debris and/or unused equipment was observed throughout the Location; including areas along the perimeter, within secondary containment, and around the housing areas.		
Corrective Action:	Comply with Rule 606.	Date:	08/07/2025

Overall Good:

Spills:

Type	Area	Volume	
Comment:	Stained soils evident across the Location.		
Corrective Action:	Comply with Rule 912.a; clean/remediation stained soils to Table 915-1 standards.	Date:	08/07/2025

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Bird Protectors			
Comment:	It was observed in this inspection that secondary containment measures are missing BMPs, or BMPs are insufficient, to prevent access by wildlife, including birds and bats.		
Corrective Action:	Comply with Rule 902.b.	Date:	08/07/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:	It was observed in this inspection that there are multiple "tanks/buckets/containers" that have filled with unknown fluids.					
Corrective Action:	Remove and properly dispose fluids within containment				Date:	08/07/2025

Paint

Condition

Other (Content)

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:	It was observed in this inspection that the secondary containment surrounding the housing on the northwest portion of the Location is filled with fluids.			
Corrective Action:	Remove and properly dispose fluids within containment.			Date: 08/07/2025

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 324752 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____ Fail _____

Comment **It was observed in this inspection that there was an insufficient amount of topsoil salvaged during re-expansion of the Location. At a minimum, 2821 CY of topsoil should have been salvaged.**

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment **It was observed in this inspection that the Topsoil stockpile was missing BMPs to protect the stockpile from wind/water erosion to minimize sediment transport, and BMPs to prevent weed establishment.**

Corrective Action **Comply with Rules 1002.c. and 1002.f. and implement BMPs to protect the stockpile from erosion, degradation, sediment transport and weed establishment.**

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____ F _____

Comment The pad was approved for expansion in 2024 into the previously interim reclaimed areas. With the area utilized for 3rd party data processing/cloud computing, this Location will not undergo any additional interim reclamation.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: It was observed in this inspection that the stormwater diversion culvert was filled with some "silty" material, potentially interfering with discharges of stormwater run-on/off.
Monitor and maintain stormwater outlets.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404302024	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7170006
712300176	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7169994