

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2025

Submitted Date:

08/13/2025

Document Number:

717100328

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Rollins, Grace On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 8960
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
 Address: 555 17TH STREET SUITE 3700
 City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Watzman, Ross		rwatzman@kpk.com	All Inspections
Neidel, Kris		kris.neidel@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452051	SPILL OR RELEASE	CL	10/30/2018		-	DAKLAK Flowline	EI

General Comment:

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 452051 and Remediation Project # 11881. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill Name: DAKLAK Flowline

Spill ID: 452051

Remediation Project #: 11881

Reported Date of Discovery: 09/02/2017

Date of Inspection: 06/03/2025

Weather: Partly cloudy, 58°F

Spill is located within or adjacent to:

- Surface water (~70 ft south)
- Riverine Wetlands (~90 ft south)
- Greater Sage Grouse Lek Site High Priority Habitat
- Greater Sage Grouse Priority Habitat Management Area High Priority Habitat
- Pronghorn Winter Concentration High Priority Habitat
- Range land (immediately adjacent, all directions)

Current site status:

- The previously observed excavation at the spill location has been backfilled and the soil stockpile has been removed.
- Salt crusting is visible across the drainage where the spill occurred, and in the drainage area down-gradient and across the access road from the spill. The salt crusting is widespread and may not be related to the spill.
- Vegetation within the spill footprint appears limited in comparison to the surrounding field.
- A line of less vegetation is visible in the approximate location of the flowline.
- Trash (a cooler) is visible adjacent to a culvert running under the access road.

See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

TRASH

Comment: Trash (a cooler) is visible adjacent to a culvert running under the access road.

Corrective Action: Comply with Rule 606.

Date: 08/20/2025

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 452051 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: Remediation Project # 11881 was created to address the ongoing remediation at the DAKLAK Flowline. The previously observed excavation at the spill location has been backfilled and the soil stockpile has been removed. Salt crusting is visible across the drainage where the spill occurred, and in the drainage area down-gradient and across the access road from the spill. The salt crusting is widespread and may not be related to the spill. Vegetation within the spill footprint appears limited in comparison to the surrounding field. A line of less vegetation is visible in the approximate location of the flowline.

Quarterly reporting is required under Remediation Project # 11881; the last Form 27 for this project was submitted 12/20/2022 and denied by ECMC on 03/28/2023 (Document # 403238795).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project # 11881. Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100329	ECMC Photo Log - DAKLAK Flowline - 06.03.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7186496