

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2025

Submitted Date:

09/08/2025

Document Number:

694500807

FIELD INSPECTION FORM

Loc ID: 435765 Inspector Name: NEIDEL, KRIS On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 95520
Name of Operator: WESCO OPERATING INC
Address: 120 S DURBIN STREET
City: CASPER State: WY Zip: 82602

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Weinert, Dave	307-577-5329	davew@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435751	TANK BATTERY	AC	01/06/2014		-	Trelevan Tank Battery	EI
439286	SPILL OR RELEASE	CL	09/10/2024		-	SPILL/RELEASE POINT	EI
491239	SPILL OR RELEASE	AC	09/05/2025		-	danforth hills field tank battery	EI

General Comment:

On 8/25/2025, ECMC staff; Kris Neidel inspected spill at the Trelevan/Danforth Hills Tank battery and Injection pump. A spill was reported on 8/24/25, spill number 491239. Weather was 80 degrees and dry. The following was observed: wet soil on the north and east side of the pump building at the reported source of spill. The water flowed to a rut in the road and followed the length of the road till it left the road and became dispersed. It appeared that Wesco staff marked the spill path with flags, the flags marked the spill appropriately, No hydrocarbon staining was observed in the spill path. Corrective Actions: The spill path shall be delineated for Table 915-1, work proceeding in the spill documents. The Tank battery at the injection facility shall be evaluated for secondary containment volume and repaired appropriately to comply with Rule 603.e. Erosion caused by the spill shall be repaired after delineation and SPCC and stormwater controls evaluated. Any corrective action(s) from previous inspections that have not been addressed are still applicable. See attached Photos

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLs	STEEL AST		
Comment:	Appears that the dirt berm has eroded on the south east corner of tank battery at Injection facility. See Photo #4.				
Corrective Action:	South east corner of the secondary containment appears has eroded and requires repair. The operator shall evaluate and repair as necessary to ensure compliance with 603.e, 150% of the largest volume tank.				Date: 09/22/2025

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	Date: <input type="text"/>

Inspected Facilities

Facility ID: 435751 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 439286 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 491239 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500808	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7222616