

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2025

Submitted Date:

09/12/2025

Document Number:

710500600

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
324798 \_\_\_\_\_ Sanchez, Chris \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 \_\_\_\_\_ Number of Comments  
 2 \_\_\_\_\_ Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 95620  
 Name of Operator: WESTERN OPERATING COMPANY  
 Address: 1165 DELAWARE STREET #200  
 City: DENVER State: CO Zip: 80204

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Hart, Dale	719-688-1638	dale@westernoperating.com	
Welsh, Brian		brian.welsh@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
James, Steven	(303) 893-2438	steve@westernoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212667	WELL	IJ	02/01/2024	DSPW	061-06027	KING-PYLES 2	EI
324798	LOCATION	AC			-	KING-PYLES-619S45W 9SWSW	EI
484889	SPILL OR RELEASE	CL	08/03/2023		-	SWD Disposal Line	EI

**General Comment:**

This is an Environmental Inspection for the King Pyles # 2 well location located in Kiowa County, CO.

Location ID 324798  
 UIC Disposal 150316  
 Well API 05-061-06027; Facility ID 212667  
 Spill Facility ID 484889  
 Remediation Project # 20716 located at Latitude 38.414630; Longitude -102.469544  
 Remediation Project # 34386 located at Latitude 38.413112; Longitude -102.471045

**Inspected Facilities**

Facility ID: 212667 Type: WELL API Number: 061-06027 Status: IJ Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 324798 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484889 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment:

This is an Environmental Inspection for Remediation Project # 20716 located at Latitude 38.414630; Longitude -102.469544 and Remediation Project # 34386 located at Latitude 38.413112; Longitude -102.471045. Both remediation projects are tied to the King Pyles # 2 well location.

At the time of inspection, Remediation Project # 20716, Historical spill along the flowline r-o-w. Initial Form 27 document no. 402861082 received on 11/04/2021, showed signs of distressed vegetation within an area fence off to keep cattle from the remediation area.

Remediation Project # 34386. There is an open excavation for Remediation Project # 34386 adjacent to the King Pyles well pad along the flowline r-o-w. At the time of inspection stormwater issues were identified at the site of the excavation with water pooling in the bottom of the excavation. The location is fenced and egress to the bottom of excavation is present. There is another excavation located @ Latitude 38.413338; Longitude -102.470950 adjacent to a flowline riser.

The Operator has provided updates for both remediation projects with the following Operator Comment: This Form 27 has been submitted as a quarterly update of activities performed at the King Pyles. This project was recently transferred to management under a different remediation consultant for completion of this project. Entrada Consulting Group, is currently in process of discovery for all documentation of actions completed under this Remediation Project. Updated project documentation, status, and/or updated remediation strategies will be provided on a subsequent Form 27.

Per records review, it appears that quarterly reporting for 2nd Quarter, 2025 was not completed. Corrective actions to prevent reoccurrence include a Form submittal tracking and notification system to alert the Operator of reporting deadlines.

Operator shall continue Quarterly Reporting until the Site Assessment is completed and the remediation areas demonstrates Compliance with Table 915-1 Standards.

Corrective Action:

In accordance with Rule 913.e.(3), Operator will adopt a quarterly reporting schedule (every 90 days) for both remediation projects.

Date: 10/23/2025

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [At the time of inspection, stormwater issues were observed at the excavation for Remediation Project # 34386.](#)

Corrective Action: [Operator shall maintain the excavation and install required stormwater BMPs in accordance with Rule 913.b.\(5\)](#)

Date: 10/13/2025

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404353087	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7231235">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7231235</a>
710500601	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7231234">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7231234</a>