

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2025

Submitted Date:

12/18/2025

Document Number:

697506050

FIELD INSPECTION FORM

Loc ID 483510 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Thibedeau, Isaac		isaac.thibedeau@state.co.us	
Elnajdi, Abdul		abdul.elnajdi@state.co.us	
,		rbucogccinspectionreports@c hevron.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483510	LOCATION	AC			-	A07-01 Pad	RI

General Comment:

This is a Stormwater Inspection. ECMC staff conducted a Stormwater Inspection along the Greeley Number 2 Canal on December 12, 2025. ECMC staff and Operator representatives conducted a Stormwater Inspection along the same area on December 17, 2025.

Location Construction

Location ID: 483510 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

Comments: Erosion BMPs:

On December 12 and 17, straw wattle BMPs were not installed per good engineering practices and were not installed per the Operator's own Site Specific Stormwater Management Plan. Project disturbances along the southern and northern Greeley Number 2 Canal were without any stormwater BMPs. Rill erosion was observed near an outlet of a culvert along a portion of the canal and likely due to the improper installation of the straw wattle BMP, which is allowing stormwater to undermine the BMP.

Other BMPs:

On December 17, FOD vehicle tracking device maintenance was being performed by pressure washing the BMP in-place, which is not the preferred maintenance per the Operator's own Site Specific Stormwater Management Plan. This maintenance approach is causing water to pool off the ROW, which is creating rill erosion and rutting that contributes to vehicle track out issues.

Refer to the attached inspection photos.

Corrective Action: Comply with Rule 1002.f.(2) to install stormwater BMPs per good engineering practices. Perform maintenance on FOD vehicle tracking devices per best management practices and repair rill erosion and rutting observed off the ROW.

Date: 12/24/2025
5

Operator may need to evaluate whether straw wattle BMPs by themselves would be sufficient to prevent stormwater erosion into the canal until adjacent project areas are stabilized.

Comment: Due to the findings on December 12 and 17, 2025, ECMC is requiring the submission of the Operator's Stormwater Inspection logs.

Corrective Action: Submit Stormwater Inspection logs since April 2025 to present.

Date: 12/24/2025

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 483510 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404479334	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7382197
697506053	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7382196