

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2026

Submitted Date:

01/15/2026

Document Number:

710500669

FIELD INSPECTION FORM

Loc ID 322227 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 44390
Name of Operator: JAVERNICK OIL
Address: 3040 E MAIN
City: CANON CITY State: CO Zip: 81212

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Javernick, Salene		salenej@gmail.com	
Javernick, Jim	(719) 275-3040	javernick1@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210044	WELL	SI	11/01/2022	OW	043-06122	SLANOVICH 32-1	EI
322227	LOCATION	AC			-	SLANOVICH-619S69W 32NWSW	EI
488874	SPILL OR RELEASE	CL	01/15/2025		-	Slanovich 32-1 Spill	EI

General Comment:

This is a follow up environmental inspection for the Slanovich 32-1 well location located in Fremont County, Colorado.
Slanovich 32-1
API #: 05-043-06122
Location ID: 322227
remediation project # 37751

Inspected Facilities

Facility ID: 210044 Type: WELL API Number: 043-06122 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 322227 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 488874 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: This is a follow up remediation inspection for Remediation Project # 37751. At the time of inspection, the access road was passible. Drill cuttings appear to have been removed from the location, and the Tank Battery appears to have been decommissioned. The last Form 27-S for remediation project # 37751 was received on 05/05/2025, document no. 404190002. This Form 27 was processed as a quarterly update for Q-2 2025 for the following reasons: ECMC has processed this form as an update; no analytical was attached thus approval of this form does not imply any agreement with comments on completion of site investigation. All ongoing/unaddressed comments/COAs from previous Forms remain applicable. Approval of this Form does not agree with any proposals within the Form.

Additional Conditions of Approval were assigned to remediation project # 37751, they are as follows:

- 1.) In accordance with Rule 913.e.(3), Operator will adopt a quarterly reporting schedule (every 90 days).
- 2.) Operator shall define the vertical and lateral extent of impacts to soil. Additional sampling is required to fully delineate the vertical and lateral impacts to soil
- 3.) Operator shall continue Quarterly Reporting until the Site Assessment is completed, and the remediation area demonstrates Compliance with Full Table 915-1 Standards.
- 4.) Operator shall update the implementation schedule in accordance with Rule 913.d on the subsequent Supplemental Form 27.

The Operator shall submit a Supplemental Form 27-S to include a current map of the subject location including current excavation limits and/or sample locations, proposed/actual soil boring locations and monitoring well locations. GPS data used to create the map must comply with ECMC Rule 216. Operator will include historical and recent soil analytical data in a table format along with photo documentation.

In addition, Operator will provide an explanation for late reporting on the next Form 27 Supplemental including actions implemented to prevent late reporting in the future.

Corrective Action: Within 14 days from receipt of this Field Inspection Report, Operator shall submit Supplemental Form 27-S for Remediation Project # 37751 in accordance with Rule 913.e. Date: 01/29/2026

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
All previously assigned Corrective Actions (CAs) from previous inspections shall apply	sanchezcc	01/15/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404508273	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7417226
710500672	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7417221