

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/27/2026

Submitted Date:

01/30/2026

Document Number:

721100092

**FIELD INSPECTION FORM**

Loc ID 326292 Inspector Name: Blair, Jamie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

**Findings:**

- 20 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone | Email                                 | Comment                  |
|------------------|-------|---------------------------------------|--------------------------|
| Blair, Jamie     |       | jamie.blair@state.co.us               |                          |
| Labowskie, Steve |       | steve.labowskie@state.co.us           |                          |
| General          |       | FarmingtonRegulatoryTechs@hilcorp.com | All SW field inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 216183      | WELL | PR     | 03/28/2000  | CBM        | 067-07789 | HUBER-NELSON 2-31 | PR          |

**General Comment:**

Southwest compliance specialist Jamie Blair performed a compliance audit and inspection of the access road an location on Monday, January 27 2026 at 4:15 pm. Any corrective actions from previous reports not addressed are still applicable.

| Location   |  |        |                 |
|--|--|--------|-----------------|
| <b>Lease Road:</b>                                     |  |        |                 |
| Type   | Access   |        |                 |
| comment:   | Access road in good condition. 2 gates with no locks. Photos 2, 3.   |        |                 |
| Corrective Action                                      |  |        | Date:           |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                 |
| <b>Signs/Marker:</b>                                   |  |        |                 |
| Type   | OTHER  |        |                 |
| Comment:   | Location sign on first gate next to house. Photo 1.  |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| <b>Emergency Contact Number:</b>                       |  |        |                 |
| Comment:   | 24 Hour: (505) 324-5170. Emergency: 911.   |        |                 |
| Corrective Action:                                     |  |        | Date: _____     |
| <b>Good Housekeeping:</b>                              |  |        |                 |
| Type   | STORAGE OF SUPL  |        |                 |
| Comment:   | Various pipes, hoses and containers of hydraulic fluid. Photos 8, 09, 10.                                    |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Type   | OTHER  |        |                 |
| Comment:   | There is hydraulic oil staining inside the hydraulic pump shed. Photos 8 & 9.                                |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Type   |  |        |                 |
| Comment:   |  |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Type   | STORAGE OF SUPL  |        |                 |
| Comment:   | Open topped plastic bucket with trash may not comply with 610.j if it contains flammable materials. Photo 9. |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| Overall Good: <input type="checkbox"/>                 |  |        |                 |
| <b>Spills:</b>   |  |        |                 |
| Type   | Area   | Volume |                 |
| In Containment: No                                     |  |        |                 |
| Comment:   |  |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                 |
| <b>Fencing/:</b>                                       |  |        |                 |
| Type   | OTHER  |        |                 |
| Comment:   | Just property line barbed wire fence on south side of well   |        |                 |
| Corrective Action:                                     |  |        | Date:           |
| <b>Equipment:</b>                                      |  |        |                 |
| Type: Bradenhead                                       | # 1  |        | corrective date |
| Comment:   | Photo 4.   |        |                 |

|                                 |   |       |                         |
|---------------------------------|---|-------|-------------------------|
| Corrective Action:              |   | Date: |                         |
| Type: Deadman # & Marked        | # 3   |       |                         |
| Comment:                        | Only 3 of four rig anchors found. All were marked. A fourth rig anchor marker was found on ground but no anchor next to it. Fourth anchor not found. Photo 11.  |       |                         |
| Corrective Action:              |   | Date: |                         |
| Type: Prime Mover               | # 1   |       |                         |
| Comment:                        | Gas-driven hydraulic. Photos 8 & 9. There is a lube-oil or secondary hydraulic reservoir drum over a secondary containmet. The secondary containment is 3/4 full. Excess fluid should be removed and properly disposed, and equipment maintained to prevent leaks and comply with 1002.F. Drum contents should should have manufacturers label.   |       |                         |
| Corrective Action:              |   | Date: |                         |
| Type: Vertical Heated Separator | # 1   |       |                         |
| Comment:                        | Photo 11, 13.   |       |                         |
| Corrective Action:              |   | Date: |                         |
| Type: Other                     | # 1   |       |                         |
| Comment:                        | Wellhead. Hydraulic oil staining and puddle of hydraulic oil on ground not E&P waste. 4, 5, and 6.  |       |                         |
| Corrective Action:              |   | Date: |                         |
| Type: Gas Meter Run             | # 1   |       |                         |
| Comment:                        | Calibration date: 09/25/2025. Observation: Mineral crust and damp floor inicates produced water leak.   |       |                         |
| Corrective Action:              |   | Date: |                         |
| Type: Flow Line                 | # 1   |       |                         |
| Comment:                        |   |       |                         |
| Corrective Action:              |   | Date: |                         |
| Type: Ancillary equipment       | # 1   |       |                         |
| Comment:                        | Telemetry   |       |                         |
| Corrective Action:              |   | Date: |                         |
| Type: Bird Protectors           | # 1   |       |                         |
| Comment:                        | on vertical heated separator stack  |       |                         |
| Corrective Action:              |   | Date: |                         |
| Type: Progressive Cavity        | # 1   |       |                         |
| Comment:                        | Hydraulically driven progressive cavity pump is hydraulic fluid. There is an area around the well head with stained soil and a small puddle of hydraulic fluid. See photos 4, 5, 6. A corrective action was issued for the same thin in inspection #721700321, dated July 21, 2023 (photo 14). Hydraulic drive and return line hoses are layed across the cener-pivot irrigation ruts on the pad (photo 7). |       |                         |
| Corrective Action:              | Securely fasten all valves, pipes, fittings, and production facilities to ensure good mechanical condition, For all hydraulic-drive system pumps, drives, reservoirs and hoses:<br>1. Inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.<br>2. Remove contaminated gravel and properly dispose to comply with 1002.f  |       | Date: <u>02/03/2026</u> |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 216183 Type: WELL API Number: 067-07789 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/08/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: [Stormwater BMPs functioning.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| <a href="#">Stains on the ground from the hydraulically driven linear progressive cavity pump, hoses, and gas-hydraulic prime mover indicate need for maintenance on pumps, hoses, and fittings. Inspection document 712700321 dated 06/22/2023 indicates that this has been an recurring issue at this location. Corrective action citations are provided in this inspection document. Less serious items are included as documentary observations. Photographs with captions are included as an attachment to this report.</a> | blairj1 | 01/27/2026 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404526513    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7433212">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7433212</a> |
| 721100093    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7433211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7433211</a> |