

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2026

Submitted Date:

04/06/2026

Document Number:

721100292

FIELD INSPECTION FORM

Loc ID 334548 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Findings:

- 22 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Huntington, Heather		hhuntington@enduringresources.com	All SW field inspections
Walker, Kyle		kwalter@enduringresources.com	All SW field inspections
Blair, Jamie		jamie.blair@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216234	WELL	PR	08/23/1992	CBM	067-07840	W ANIMAS-UNIVERSITY 9-1	PR
264265	WELL	PR	11/01/2002	CBM	067-08741	WEST ANIMAS-UNIVERSITY 9-3	PR

General Comment:

On Friday, April 3, 2026 at 12:50 PM, Southwest Compliance Specialist Jamie Blair performed a producing well compliance inspection and audit. Both wells were operating at the time of the inspection. Corrective actions pertaining to hydraulic fluid stained gravel and rig anchor markers identified. Photos of the inspection are linked in the attachments section of this report. Any previously identified corrective actions remain applicable.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	West Animas University 9-1 - Photo 1		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	West Animas University 9-3 - Photo 2		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency Contace 1-800-916-7897 or 911.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	OTHER		
Comment:	There are several pin flags on the ground, some standing and some knocked over, presumably to mark buried flow line or electrical lines or other utilities. They should be picked up when no longer needed.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained gravel beneath hydraulic linear rod pump on well 9-3. Photo 15, 16.		
Corrective Action:	Cleanup stained material and dispose in approved manner, and review self inspection processes to comply with 1002.f.(2).D.	Date:	04/13/2026
Type	UNUSED EQUIPMENT		
Comment:	equipment shield and worker barrier not in use. Photo 15.		
Corrective Action:	Remove or return to service to comply with 606.	Date:	05/04/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Location is surrounded by 8 foot tall 3 barbed-wire strand topped chain link fence with green plastic slat visual barrier.		
Corrective Action:		Date:	
Equipment:			
Type: Ancillary equipment # 2			corrective date
Comment:	2 chemical treatment containers on top of containment.		
Corrective Action:		Date:	
Type: Pig Station # 1			
Comment:			

Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric for traditional pump jack Electric/hydraulic for hydraulic liner rod pump jack.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	9-1 well = 2/11/2026 calibration date 9-3 well = 5/19/2025 calibration date		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Buried valve access box made of steel culvert.		
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	2 above ground by meter runs. 1 line in SE corner downstream of meter with pig station next to underground valve access box.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Solar telemetry at each chemical container and meter run.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	3 not properly marked. 2 at south end, 1 at north end. Photos 14, 19, 20.		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: <u>05/04/2026</u>
Type: Pump Jack	# 2		
Comment:	05-067-07840 Animas University 9-1 - Traditional style 05-067-08741 Animas University 9-3 - Linear rod pump with electric driven vertical hydraulic lifter. Hydraulic fluid is leaking from hose fittings and/or hydraulic ram, resulting in stained soil. Photos 15, 16, 17.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>04/13/2026</u>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216234 Type: WELL API Number: 067-07840 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/03/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 264265 Type: WELL API Number: 067-08741 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/03/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Ditches	Pass					
Berms	Fail					
Compaction	Pass	Compaction	Pass			

Comment: [Ground surface on location was soft due to recent rains and had seasonal rutting. No signs of erosion or sediment moving off site. There is a 3 foot tall gravel berm outside the chainlink fence surrounding the well pad. It is compromised by a 6 inch diameter animal burrow in the northeast corner. Note: burrow looks like it may be actively used, possibly a badger or marmot. Photos 25, 26.](#)

Corrective Action: **Repair required BMPs per Rule 1002.f.(2)C.**

Date: 05/04/2026

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Corrective actions identified. See photographs linked in attachments.	blairj1	04/03/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404609217	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7505819
721100297	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7505816