

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2026

Submitted Date:

04/10/2026

Document Number:

721100307

FIELD INSPECTION FORM

Loc ID 311886 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10840
Name of Operator: ABUNDANCE ENERGY SERVICES LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

Findings:

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
GENERAL		jepugh@abundance-energy.com	
GENERAL		aprice@abundance-energy.com	
GENERAL		sjbcompliance@abundance-energy.com	
Blair, Jamie		jamie.blair@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89102	WELL	PR	02/23/2000	GW	067-08206	ARVIL BROWN 1A	PR
89120	WELL	PR	09/01/2024	GW	067-08224	ARVIL BROWN DK 1A-R	PR

General Comment:

On Monday, April 6, 2026 at 11 AM, southwest compliance inspector James Blair performed a location inspection and audit of the Avril Brown N33N9W 15SWNE Location which contains Abundance Energy Avril Brown 1A, and Avril Brown DK 1A-R wells. The wells share a location with the Simcoe Avril Brown 3 well. Corrective actions pertaining to storm water BMPs were identified. Water that flows down the access road is diverted onto the site causing damage to storm water BMPs and flooding the site during runoff events. Photos are linked as an attachment.

The inspection was initiated when Abundance submitted a form 6 and form 42 to plug and abandon the Avril Brown KD 1A-R well at 12:00 PM April 6, 2026. The ECMC compliance specialist arrived by the specified time, but no equipment was on site, so the inspection was initiated. A form 6 and form 42 reflecting a later start date were subsequently submitted. The operator should withdraw all forms pertaining to plugging and abandonment that no longer have applicable start dates and times.

Location			
Lease Road:			
Type	Main		
comment:	Water is diverting from county road onto location. Address issue before plugging and abandonment operations. A long term solution to this problem will require working with the designated road authority to maintain the road in such a way that water from the road no longer flows onto the pad. See photos 13, 14, 17, 18, 19. See stormwater section for related CA's.		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	In front of wellheads. Photos 2, 3, 4. Note that spelling of names on sign does not match well names in ECMC Database.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	800-452-1578 (verified by calling) Emergency 911		Date:
Corrective Action:			Date:
Good Housekeeping:			
Type	DEBRIS		
Comment:	non-functional straw wattle debris on north and south edge. Dispose of any wattle debris that cannot be reused.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	4 foot tall 4 inch wire mesh and T-post fence with turnstyle gate.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Other	# 2		
Comment:	Wellheads		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	Separators to meter runs		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	accessible		

Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	1A-R: Meter cal card indicates "removed from service" on 5/1/25 1A: Meter cal = 4/16/25		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	solar telemetry on meter run shed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.106430,-107.800919
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	30 BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 89102 Type: WELL API Number: 067-08206 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/28/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: accessible

Corrective Action:

Date:

Facility ID: 89120 Type: WELL API Number: 067-08224 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/25/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: accessible

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Water flows down the access road (Black Hawk Trl), & diverts off road & onto the location pad. Sediment has filled up the run-on diversion ditch, downcut the associated berm, & undercut straw wattles, so stormwater flows directly onto pad at Abundance meter run shed, & deposits fan of sediment, at S. end of the pad. At N. end of pad, there is evidence of erosion where water exits the pad, and sediment carried off site into a grassy area non-functional straw wattles. Long term solution will require coordination with the designated road authority for Blackhawk trail to address the water diversion. Address issue prior to mobilizing equipment for plugging and abandonment. Photos 12 to 20.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C and minimize stormwater run-on and flowing through location and associated sediment migration.

Date: 05/26/2026

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Work with designated road authority to adress storm water diversion from road onto site. Address storm water issues prior to plugging and abandonment or other activities involving large equipment on site over multiple days.	blairj1	04/09/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404616099	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511641
721100309	Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7511639