

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/13/2026

Submitted Date:

04/15/2026

Document Number:

717100520

FIELD INSPECTION FORM

Loc ID 452180 Inspector Name: Rollins, Grace On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
Anderson, Laurel		laurel.anderson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452180	LOCATION	AC			-	Wilson IC Pad	EI
493005	SPILL OR RELEASE	AC	02/04/2026		-	Wilson IC	EI

General Comment:

[ECMC Field Inspection Report Summary](#)
This is an environmental inspection to determine progress on Spill ID 493005. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. Photos attached to document site conditions.

Site/Spill Name: [Wilson IC](#)
Spill ID: [493005](#)
Location ID: [452180](#)
Reported Date of Discovery: [01/29/2026](#)
Date of Inspection: [04/13/2026](#)
Weather: [Partly cloudy, 66°F](#)

Current site status:

- The excavation at the spill location has been backfilled.
- A bucket with fluid has been placed beneath a valve and pipe on the west side of the separator. Installed pressure gauge shows 12 psi.
- Residue is visible on a valve, pipe, and the separator on the east side of the separator. Installed pressure gauge shows 0 psi. Stained soil is visible beneath the valve. A petroleum hydrocarbon odor is observed when the stained soil is disturbed.

See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Horizontal Separator	#		
Comment:	A bucket with fluid has been placed beneath a valve and pipe on the west side of the separator. Installed pressure gauge shows 12 psi. Residue is visible on a valve, pipe, and the separator on the east side of the separator. Installed pressure gauge shows 0 psi.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 04/29/2026

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 452180 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 493005 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: A bucket with fluid has been placed beneath a valve and pipe on the west side of the separator. Stained soil is visible beneath the valve on the east side of the separator. A petroleum hydrocarbon odor is observed when the stained soil is disturbed.

Corrective Action: Comply with ECMC Rules. Operator shall immediately control and contain spills/releases and investigate, clean up and document impacts per Rule 912.a. Note: for any spills that do not meet the reporting requirements of Rule 912.b.; Operator shall provide documentation of the cleanup efforts (photo documentation and waste disposal manifests) to the Director per Rule 912.a.(5) - Operator may submit documentation via FIRR. Additionally, Operator shall properly handle, transport and dispose of E&P waste in accordance with 905 Series Rules. Date: 05/15/2026

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Spill ID 493005 was created to address the remediation of impacts identified at the Wilson IC separator. The excavation at the spill location has been backfilled.

Corrective Action: Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404620671	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515091
717100521	ECMC Photo Log - Wilson IC - 04.13.2026	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7515087