

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2026

Submitted Date:

05/11/2026

Document Number:

701104763

FIELD INSPECTION FORM

Loc ID 335654 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262593	WELL	PR	05/25/2002	GW	045-08039	CHEVRON GM 31-17	EG
289525	WELL	PR	02/28/2007	GW	045-13777	CHEVRON GM 531-17	EG
289526	WELL	PR	02/28/2007	GW	045-13776	CHEVRON GM 32-17	EG
289527	WELL	PR	02/28/2007	GW	045-13775	CHEVRON GM 431-17	EG
289528	WELL	PR	02/28/2007	GW	045-13774	CHEVRON GM 331-17	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
One of the fence panels and sign are laid over on the ground.
Reinstall fence and sign.
Pipes, fittings and valves on the separators have rust and corrosion. The 5 - 2" ball valves on the front of each separator unit have no plugs and have rust and corrosion. Single separator unit has no plug in ball valve for the glycol vessel.
Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.
Comply with Rule 603.i.
CA Date 05/29/2026
Paint deterioration and areas of rust around the bottom of tank. Bottom bolts on man hatch are severely rusted.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	One of the fence panels and sign are laid over on the ground. Reinstall fence and sign.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type:	Horizontal Heated Separator	# 5	
Comment:	Pipes, fittings and valves on the separators have rust and corrosion. The 5 - 2" ball valves on the front of each separator unit have no plugs and have rust and corrosion. Single separator unit has no plug in ball valve for the glycol vessel.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. Comply with Rule 603.i..		Date: 05/29/2026

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	Paint deterioration and areas of rust around the bottom of tank. Bottom bolts on man hatch are severely rusted.				
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: <u>262593</u>	Type: <u>WELL</u>	API Number: <u>045-08039</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>289525</u>	Type: <u>WELL</u>	API Number: <u>045-13777</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>289526</u>	Type: <u>WELL</u>	API Number: <u>045-13776</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>289527</u>	Type: <u>WELL</u>	API Number: <u>045-13775</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>289528</u>	Type: <u>WELL</u>	API Number: <u>045-13774</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104764	Flowline integrity inspection 701104763 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7545668