Plugging Procedure

Codell

Existing Perforations:

Codell: 7310’-7326’

PBTD: 7481'

8 5/8" 24# Casing set @ 464' cemented w/ 350 sx

4 1/2" 11.6# Casing set @ 7481' cemented w/ 250 sx

Procedure:

1)MIRU WO Rig

2)TOH w/ production tubing

3)MIRU wireline

4)RIH w/CIBP set @ 7250’

5)RIH w/dump bailer and dump 2 sx cement on top of CIBP

6)RIH w/casing cutter, cut & pull casing @ ~6600’

7)TIH set 50 sack plug @ casing stub (6600’)

8)TIH to tag stub plug

9)TOH to set 200 sack plug @ Parkman/Sussex (~3500’-~4200’)

10)TOH and set 200 sack cement plug 500' to surface

11)Set 10 sx @ top of surface

12)Cut casing and weld on cap