General Comments

User Group	Comment	Comment Date

Total:

Pre-Job:
Notify land owner and COGCC 10 days prior to RU
Hold Safety Meeting
Move in rig tank and pump with 130 bbls fresh water
Move in trailer for laying down 3/4" rods and 2 3/8" tubing.

Job

1). MIRU WO Rig
2). POOH 183 jts. 3/4" rods and 2-6' rod subs and lay down.
3). Switch over to 2 3/8" tbg tools.
4). POOH 142 jts 2 3/8" tbg w/ SN. Lay dowh.
5). RUWL
6). RIH and set CIBP @ +/- 4,540'.
7). Dump bail 2 sx cement.
8). Fill hole with water.
9). RIH and perforate (2 SPF @ 1 ft.) @ +/- 750'.
10). Pump 40 sx cement.
11). POOH 3 jts. and flush with 5 bbls. water.
12). WOC and tag plug.
13). Fill hole with water and set surface plug from 100' to surface.
14). ND BOP and remaining wellhead
15). RDMO WO Rig
16). Dig out and cut off wellhead 4' below surface, weld plate onto casing
17). Clear equipment
18). Reclaim land

Post-Job

File P&A reports with COGCC and notify landowner