WORKOVER PROCEDURE

WELL NAME:	KY H25-24			**DATE:**	3/7/2016		
LOCATION:							
Qtr/Qtr:	SW/SE	Section:	25	Township:	3N	Range:	65W
Footages:	1300' FSL	&	2567' FEL				
COUNTY:	WELD	STATE:	CO			API #:	05-123-24447

ENGINEER:	Benjamin Daniell	7 Day Notice Sent:	
	(Please notify Engineer of any major changes prior to work)	Do not start operations until:	
		Notice Expires:	

OBJECTIVE: P&A

WELL DATA:	Surface Csg:	8 5/8" 24# J-55 @ 679'		KB Elevation:	4816'
	Surface Cmt:	340 sx		GL Elevation:	4804'
	Long St Csg:	4 1/2" 11.6# M-80 @ 7628'		TD:	7681'
	Long St Cmt:	650 sx		PBTD:	7626'
	Long St Date:	12/4/2006			
	Plug Back (Sand or CIBP):				
	Perforation Interval (1):	Niobrara Perforations 6820' - 6838'			
	Perforation Interval (2):	Codell Perforations 7057' - 7069'			
	Perforation Interval (3):				
	Tubing:	2-3/8" 4.7# J-55 @ 7044'	Rods:	NA	
	Pump:	NA			
	Misc.:				

PRODUCTION STATUS: Producing
COMMENTS: In the ROW of Tri-State's planned power line; Producing Sussex within 1 mile

PROCEDURE:

1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 6770', dump bail 2 sx of cement on top.
4) RIH w/ workstring to pump 30 sx balance plug @ 4500' to isolate Sussex. If maintain circulation, no need to tag plug.
5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
7) POOH w/ workstring to 779'. Pump 255 sx shoe plug. Cement to surface.
8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
9) Cut surface casing off 6'-8' below ground.
10) Clean up location. Reclaim location. RDMO.