FORM INSP Rev X/20

State of Colorado
Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM

Inspection Date: 09/05/2025
Submitted Date: 09/17/2025
Document Number: 713602410

Loc ID: 321654
Inspector Name: COSTA, RYAN
On-Site Inspection: ☐
2A Doc Num:

Status Summary:

☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
3 Number of Corrective Actions
☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 96730
Name of Operator: WILLIFORD ENERGY COMPANY
Address: 6060 AMERICAN PLAZA SUITE 760
City: TULSA State: OK Zip: 74135

Contact Information:

Contact Name	Phone	Email	Comment
Storts, Doug	(918) 495-2710	pds@willifordenergy.com	
Growns, Larry		lgrowns@willifordenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207690	WELL	PR	10/19/1986	OW	017-06625	RHOADES UNIT 5-5	RI

General Comment:

This is a follow up reclamation inspection of the RHOADES Unit #5-5 wellsite.
See attached photos and additional details within this report.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			
	WELLHEAD				
Comment:	The spill that was initially observed on 3/26/24 has not been cleaned up. There are still stained soils around the wellhead and southwest of the well that have not been cleaned up and properly disposed. There has been no form 19 spill report submitted to report the spill. Previous corrective action was not completed.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste or produced fluids Remove free fluids and contact EPS staff per Rule 912.b.			Date:	
	Pump Jack				
Comment:	The leaking engine motor has been removed since the previous inspection. There is still stained soils at the base of the pumpjack that have not been cleaned up. Previous CA was not completed.				
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906			Date:	

In Containment: No

Comment:

☐ Multilple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are still areas of the access road that are not stabilized or maintained. There has been a road base material applied onto areas of the road however, this material has not been graded, crowned, or compacted. The access road needs to be repaired and maintained with BMP's installed per good engineering practice. Previous corrective action has not been completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
713602411	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7240969