0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/03/24	Operator	Bison Operating IV
Field:			
County:	Weld		
Operation:	P & A		

Well Name:	Speaker L		API # 05-123-14369
Consultant:	Rusty Tucker	AFE #:	
Phone:	970-380-2326	Csg Depth / TD:	
Rig Contractor:	United #44	Size / Grade:	
Location:		Weight / Thread:	
Lat/Long:	40.616415 / -104.180325	Perforations:	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
7:45	9:00	1:15	Roustabouts arrived & dug down to well and cut off the cap
9:00	11:00	2:00	Welded pipe & collar on to bring up to ground level, filled hole
11:00	11:45		Spot the basebeam & RU the rig, spot mud system
11:45	16:00	4:15	NUBOP and rig up TBG tools, lay lines from the pump & tank, RU the power swivel, move drill collars and TBG to racks & tally. SDFN
16:00			

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top
			End of Tubing:		

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/04/24	Operator	Bison Operating IV	Well Name:	Speaker L		API # 05-123-14369
Field:				Consultant:	Rusty Tucker	AFE #:	
County:	Weld			Phone:	970-380-2326	Csg Depth / TD:	
Operation:	P & A			Rig Contractor:	United #44	Size / Grade:	
				Location:		Weight / Thread:	
				Lat/Long:	40.616415 / -104.180325	Perforations:	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
			Crew travel
6:30	10:45	4:15	PU 6 1/4" bit, 10 drill collars & started drilling cement @ surface, drilled spotty cement down to 150' and tagged 2nd plug @ 700'
10:45	14:20		Dilled and circulated down to 1,100', had stringers & cement mixed with mud down to 950', circulated clean
14:20	15:15	0:55	POOH, lay down bit & drill collars
15:15	20:30	5:15	RIH w/2 7/8" TBG & notched collar, circulated down to 2,815', circulate clean & POOH to surface CSG. SWI & SDFN.
20:30			Crew travel

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top
			End of Tubing:		

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/05/24	Operator	Bison Operating IV	Well Name:	Speaker L	API # 05-123-14369
Field:				Consultant:	Rusty Tucker	AFE #:
County:	Weld			Phone:	970-380-2326	Csg Depth / TD:
Operation:	P & A			Rig Contractor:	United #44	Size / Grade:
				Location:		Weight / Thread:
				Lat/Long:	40.616415 / -104.180325	Perforations:

BREAKDOWN OF OPERATIONS / TUBING, BHA, Rods

From	To	Hrs	Description	Quantity	OD	ID	Description	Length	Top
			Crew travel						
6:30	9:00	2:30	RIH to 2,815 & circulated, got a lot of heavy mud and chunks of mud back, looks like the thinner mud loosened up the mud overnight.						
9:00	12:00		Continued RIH and circulated to 4,472'						
12:00	15:00	3:00	Continued RIH and circulated to 6,135'						
15:00	16:30	1:30	Continued to RIH to TD						
16:30	19:00	2:30	Circulated clean						
19:00	21:00	2:00	POOH to surface CSG, SWI & SDFN						
21:00			Crew travel						
							End of Tubing:		

Schneider Summit Services

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/06/24	**Operator**	**Bison Operating IV**	**Well Name:**	**Speaker L**		API # 05-123-14369
Field:				**Consultant:**	Rusty Tucker	**AFE #:**	
County:	Weld			**Phone:**	970-380-2326	**Csg Depth / TD:**	
Operation:	P & A			**Rig Contractor:**	United #44	**Size / Grade:**	
				Location:		**Weight / Thread:**	
				Lat/Long:	40.616415 / -104.180325	**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
			Crew travel
6:30	8:45	2:15	RIH to 835' & tagged something we couldn't get through, PU the power swivel & couldn't make any hole with the notched collar
8:45	10:00	1:15	POOH w/TBG, PU 6 1/4" bit, 5 drill collars & RIH w/TBG
10:00	11:00	1:00	RU power swivel & start drilling, drilled through & circulated down to 1,030'. Didn't see anything on the shakers to indicate what we tagged
11:00	11:40	0:40	POOH, LD drill collars & bit
11:40	12:30	0:50	RIH w/notched collar & TBG. Tagged @ 1,150', couldn't get past it
12:30	14:00	1:30	POOH, changed the notched collar for a mule shoe & RIH, no luck
14:00	15:00	1:00	POOH, found about 1 1/2' of dry drilling mud packed in the end of TBG
15:00	16:00	1:00	Looked for a pumpoff sub for the drill bit. SWI & SDFN
16:00			Crew travel

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top
				End of Tubing:	

0:00
58.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/07/24	**Operator**	**Bison Operating IV**	**Well Name:**	**Speaker L**	API # 05-123-14369
Field:				**Consultant:**	Rusty Tucker	**AFE #:**
County:	Weld			**Phone:**	970-380-2326	**Csg Depth / TD:**
Operation:	P & A			**Rig Contractor:**	United #44	**Size / Grade:**
				Location:		**Weight / Thread:**
				Lat/Long:	40.616415 / -104.180325	**Perforations:**

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
			Crew travel
6:30	8:45	2:15	PU 4 3/4" bit, pump off bit sub & RIH w/TBG to 2,500' & circulate
8:45	10:45	2:00	RIH to 5000' & circulate
10:45	13:00	2:15	RIH to TD of 7,146 & circulate
13:00	15:00	2:00	RU Magnum Cementers, drop the ball, pumped off the bit sub and pump 65 sks of 15.8#, 1.15 Y class G cement, displace & POOH to 6,459'
15:00	20:30	5:30	Pump 100 sks of 15.8#, 1.15 Y class G cement, displace and POOH to 1,690'
20:30	0:50	4:20	Pump 100 sks of 15.8#, 1,15 Y Cass G cement, displace, LD 10 JTS, circulate clean, stand back 13 stands & wait
0:50	2:00	1:10	RIH & tag cement @ 1,390', POOH to 669'
2:00	6:00	4:00	Pump 100 sks of 15.8#, 1.15 Y class G cement, displace, POOH & wait on cement

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top

End of Tubing:

0:00
57.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/08/24	**Operator**	**Bison Operating IV**	**Well Name:**	**Speaker L**		API # 05-123-14369
Field:				**Consultant:**	Rusty Tucker	**AFE #:**	
County:	Weld			**Phone:**	970-380-2326	**Csg Depth / TD:**	
Operation:	P & A			**Rig Contractor:**	United #44	**Size / Grade:**	
				Location:		**Weight / Thread:**	
				Lat/Long:	40.616415 / -104.180325	**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
6:00	7:00	1:00	Wait on cement
7:00	11:45	4:45	Tag cement @ 766', POOH to 660', order more cement & wait for it to arrive
11:45	16:00	4:15	Pump 100 sks of 15.8#, 1.15 Y of class G cement w/2% calcium, POOH & wait 4 hrs.
16:00	17:30	1:30	RIH & tag cement @ 766' POOH to 660 and pumped 135 SKS of 15.8#, 1.15Y of class G cement, LD TBG
17:30			Crew travel

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top
			End of Tubing:		

Schneider Summit Services

0:00
57.00

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/09/24	**Operator**	**Bison Operating IV**	**Well Name:**	**Speaker L**		API # 05-123-14369
Field:				**Consultant:**	Rusty Tucker	**AFE #:**	
County:	Weld			**Phone:**	970-380-2326	**Csg Depth / TD:**	
Operation:	P & A			**Rig Contractor:**	United #44	**Size / Grade:**	
				Location:		**Weight / Thread:**	
				Lat/Long:	40.616415 / -104.180325	**Perforations:**	

BREAKDOWN OF OPERATIONS

From	To	Hrs	Description
			Crew travel
9:30	10:15	0:45	RIH & tag cement @ 470', POOH to 100'
10:15	11:30	1:15	RU Magnum cementers, pump 69 sks of 15.8#, 1.15 Y, class G cement to surface
11:30	15:30	4:00	RD cementers & rig equipment
15:30			Crew travel

TUBING, BHA, Rods

Quantity	OD	ID	Description	Length	Top

0:00
57.00

Schneider Summit Services

Schneider Summit Services
PO Box 983038
Park City, UT 84098

DAILY OPERATIONS REPORT

Date (1st Hour):	06/17/24	**Operator**	**Bison Operating IV**	**Well Name:**	**Speaker L**		API # 05-123-14369
Field:				**Consultant:**	Rusty Tucker	**AFE #:**	
County:	Weld			**Phone:**	970-380-2326	**Csg Depth / TD:**	
Operation:	P & A			**Rig Contractor:**	United #44	**Size / Grade:**	
				Location:		**Weight / Thread:**	
				Lat/Long:	40.616415 / -104.180325	**Perforations:**	

BREAKDOWN OF OPERATIONS				**TUBING, BHA, Rods**					
From	**To**	**Hrs**	**Description**	**Quantity**	**OD**	**ID**	**Description**	**Length**	**Top**
			MIRU RIVAL ROUSTABOUT CREW AND WELDER.						
9:30	10:15	0:45	PERFORM 30 MINUTE BUBBLE TEST ON CASING.						
10:15	11:30	1:15	DIG UP CASING. CUT CASING OFF 6' BELOW GROUND LEVEL.						
11:30	15:30	4:00	WELD ON IDENTIFYING CAP.						
15:30									