

Project 678  
appendix A

1/18/2001  
report




Photo 1 – View of Tow Creek Bridge looking west.



Photo 2 – View looking north at south bridge abutment.



Photo 3 – View looking south across the Tow Creek Bridge in August 2000.



Photo 4 – View looking south across the Tow Creek Bridge in August 2000.



Photo 5 – View looking south in August 2000 (low water) at pipeline with damaged insulation.



Photo 6 – View looking south in April 1999 (high water) at pipeline and damaged insulation.



Photo 7 – Close up view of opened seam in metal jacket around asbestos insulation



Photo 8 – Close up view of seam in jacket around asbestos insulation.