


**PIT STATUS EVALUATION FORM**

Facility ID: 115089

Pit Name: WHITEHEAD 4-11

Duplicate Record(s) Pit #



**Legend**

- Producing or Shut In Well
- ⚡ Temp Aban Well
- ⚡ Abandoned Well
- ⚡ Dry & Aban Well
- ⊛ Earthen Pit
- Culvert
- ✱ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:  
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

**COGCC Database Information**

Status: NR Owner: RENEGADE OIL & GAS COMPANY LLC  
 T: 6S R: 62W Sec: 4 QQ: NESW 6th Meridian  
 Latitude: 39.554579 Longitude: -104.340356 NAD83

County: Elbert, CO  
 County Code: 039

**Pit Status Evaluation**

- Active**
- Form 15: Pit Permit (1983) existing Assoc. Well Seq No(s) 06277 pr (3-16-78)
  - Other documentation FIR# 200124015 (6-2007)
  - Aerial photo verification
- Closed**
- Form 27: Remediation Workplan \_\_\_\_\_
  - Form 4: Sundry Notice \_\_\_\_\_
  - Rule 903a.(2)B
  - Evidence pit(s) existed, no closure docs & well not PR, AC or SI  
Well API Seq #(s) \_\_\_\_\_
  - Other documentation \_\_\_\_\_
- Abandoned**  Possible un-reclaimed pit(s) or adverse conditions, no closure docs  Site Visit
- Unknown**  No Site Visit  Add'l Review

Notes: FIR (5-1996) indicates earthen overflow pit & buried metal skim tank  
FIR (6-15-2007) indicates 3,200 BBL upngnts #200124015  
FIELD VISIT 6-4-2008 : PIT BACKFILLED. SITE CLEAN



Photo 1. Whitehead 4-11 wellhead and lease sign



Photo 2. Looking east at three 300 BBL tanks and separator



**Photo 3. Looking north at former location of pit in foreground of wellhead**

**PIT STATUS EVALUATION FORM**

Facility ID: 115091  
 Pit Name: HAY 4-5

Duplicate Record(s) Pit #



**Legend**

- Producing or Shut In Well
- ⚡ Temp Aban Well
- ⚡ Abandoned Well
- ⚡ Dry & Aban Well
- ★ Earthen Pit
- Culvert
- ★ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:  
 USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPANOPULOS & ASSOCIATES, INC.

**COGCC Database Information**

Status: NR Owner: RENEGADE OIL & GAS COMPANY LLC  
 T: 6S R: 62W Sec: 4 QQ: SWNW 6th Meridian  
 Latitude: 39.557821 Longitude: -104.344921 NAD83

County: Elbert, CO  
 County Code: 039

**Pit Status Evaluation**

**Active**       Form 15: Pit Permit (1983) existing      Assoc. Well Seq No(s) 06279 PR  
 Other documentation MAP # 690501 (6-21-1983)  
 Aerial photo verification

**Closed**       Form 27: Remediation Workplan \_\_\_\_\_  
 Form 4: Sundry Notice \_\_\_\_\_  
 Rule 903a.(2)B \_\_\_\_\_  
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI  
                                  Well API Seq #(s) \_\_\_\_\_  
 Other documentation \_\_\_\_\_

**Abandoned**       Possible un-reclaimed pit(s) or adverse conditions, no closure docs       Site Visit  
 **Unknown**       No Site Visit  
 Add'l Review

Notes: FIELD VISIT 6-4-2008: Found fiberglass tank, concrete vault & earthen pit. Recent earthwork on pit; not covered; no oil & sparse e; no fence. Recommend pit closure if not in use.



Photo 1. Fiberglass water tank and concrete vault in background



Photo 2. Looking southwest at separator



**Photo 3. Looking northwest at Hay 4-5 wellhead**



**Photo 4. Looking southwest at earthen pit and concrete vault**



Photo 5. Looking east at earthen pit



Photo 6. Concrete vault





Photo 1. Whitehead 1 battery tank lease sign



Photo 2. Looking north showing part of the former pit site to the west of the lease road



**Photo 3. Backfilled pit area, formerly two 40'x40' pits and one 75'x50' pit**



**Photo 4. Looking east across from former pits at possible impacts from water drainage under road culvert**



**Photo 5. Looking southwest towards former pits showing possible vegetation impacts**





Photo 1. Morris 33-18 #1 Battery tank lease sign



Photo 2. Looking south towards former pit site



Photo 3. Vertical separator found adjacent to CO RD 65


**PIT STATUS EVALUATION FORM**

Facility ID: 115096

Pit Name: WHITEHEAD 18-4

Duplicate Record(s) Pit #

119945



**Legend**

- Producing or Shut In Well
- ⚡ Temp Aban Well
- ⚡ Abandoned Well
- ⚡ Dry & Aban Well
- ⊛ Earthen Pit
- Culvert
- \* Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence



Image Source:  
USDA National Agricultural Imagery  
Program (NAIP), 2006

S.S. PAPANOPULOS & ASSOCIATES, INC.

**COGCC Database Information**

Status: NR Owner: RENEGADE OIL & GAS COMPANY LLC  
T: 6S R: 62W Sec: 18 QQ: NWNW 6th Meridian  
Latitude: 39.534871 Longitude: -104.382768 NAD83

County: Elbert, CO  
County Code: 039

**Pit Status Evaluation**

- Active**  Form 15: Pit Permit #690672 #847317 (1983) & existing Assoc. Well Seq No(s) 06238 PR(2-04)  
 Other documentation \_\_\_\_\_  
 Aerial photo verification \_\_\_\_\_
- Closed**  Form 27: Remediation Workplan \_\_\_\_\_  
 Form 4: Sundry Notice \_\_\_\_\_  
 Rule 903a.(2)B \_\_\_\_\_  
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI  
 Well API Seq #(s) \_\_\_\_\_  
 Other documentation \_\_\_\_\_
- Abandoned**  Possible un-reclaimed pit(s) or adverse conditions, no closure docs  Site Visit  
 **Unknown**  No Site Visit  
 Add'l Review

Notes: LIF #690673(8-87) 30'x30' wire covered, unlined pit, Pictures (1999)  
FIELD VISIT 6-4-2008: PIT BACKFILLED  
found covered steel tank for water storage



Photo 1. Whitehead 18-4 tank battery lease sign



Photo 2. Battery tank and covered steel water tank



**Photo 3. Looking east at former pit site beyond vertical separator**



**Photo 4. Backfilled pit site**



**Photo 5. Looking east at backfilled pit site in foreground**





Photo 1. Covered fiberglass water tank



Photo 2. Champlin 416 Amoco "C" 1 wellhead



**Photo 3. Horizontal separator**



**Photo 4. Looking north from the southwest corner of the wellpad**



**Photo 5. Looking northeast from the southwest corner of well pad.  
The former pit site may have been at the southeast corner of the well pad (right in photo).**

**PIT STATUS EVALUATION FORM**

Facility ID: 115104

Pit Name: EVERITT 43-19

Duplicate Record(s) Pit #



**Legend**

- Producing or Shut In Well
- ♂ Temp Aban Well
- ♂ Abandoned Well
- ♂ Dry & Aban Well
- ☀ Earthen Pit
- Culvert
- ✱ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:  
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

**COGCC Database Information**

Status: NR Owner: CRIMSON EXPLORATION OPERATING INC  
 T: 6S R: 64W Sec: 19 QQ: NESE 6th Meridian  
 Latitude: 39.511481 Longitude: -104.589082 NAD83

County: Elbert, CO  
 County Code: 039

**Pit Status Evaluation**

- Active  Form 15: Pit Permit (12-1985) existing Assoc. Well Seq No(s) 06506 (8-9-85) PK  
 Other documentation \_\_\_\_\_  
 Aerial photo verification \_\_\_\_\_
- Closed *fiberglass tank*  Form 27: Remediation Workplan \_\_\_\_\_  
 Form 4: Sundry Notice \_\_\_\_\_  
 Rule 903a.(2)B \_\_\_\_\_  
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI  
 Well API Seq #(s) \_\_\_\_\_  
 Other documentation \_\_\_\_\_
- Abandoned  Possible un-reclaimed pit(s) or adverse conditions, no closure docs  Site Visit  
 Unknown  No Site Visit  
 Add'l Review

Notes: LIF (10-15-1985) skim 20'x20', FIR (10-31-1996) pit existing.  
FIR (9-2007) #2001242278 no pit mentioned  
FIELD VISIT 6-3-2008: PIT BACKFILLED. Using fiberglass tank

PIT STATUS EVALUATION FORM

Facility ID: 115108

Pit Name: NEIRA 8-3 & 8-11

Duplicate Record(s) Pit #



**Legend**

- Producing or Shut In Well
- ⚡ Temp Aban Well
- ⚡ Abandoned Well
- ⚡ Dry & Aban Well
- ☀ Earthen Pit
- Culvert
- ✱ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Seperator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:  
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

**COGCC Database Information**

Status: NR Owner: PETROPLEX EQUIPMENT INC  
 T: 6S R: 62W Sec: 8 QQ: NESW 6th Meridian  
 Latitude: 39.540447 Longitude: -104.359402 NAD83

County: Elbert, CO  
 County Code: 039

**Pit Status Evaluation**

- Active**       Form 15: Pit Permit (1983) existing      Assoc. Well Seq No(s) \_\_\_\_\_  
 Other documentation \_\_\_\_\_  
 Aerial photo verification \_\_\_\_\_
- Closed**       Form 27: Remediation Workplan \_\_\_\_\_  
 Form 4: Sundry Notice #690600 (3-7-85) earthen pit cancelled  
 Rule 903a.(2)B \_\_\_\_\_  
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI  
     Well API Seq #(s) 06314 PA (4-20-1987)  
 Other documentation WSIF #436575 (4-20-1987)
- Abandoned**       Possible un-reclaimed pit(s) or adverse conditions, no closure docs       Site Visit  
 **Unknown**       No Site Visit  
 Add'l Review

Notes: Sundry Notice (1985) installed underground steel water storage tank.  
WSIF (1987) indicates pits NOT backfilled & site NOT clean.  
FIELD VISIT 6-4-2008: PIT BACKFILLED. & SITE RECONTOURED.

PIT STATUS EVALUATION FORM

Facility ID: 115109

Pit Name: WHITEHEAD 8-5 & 8-15

Duplicate Record(s) Pit #



**Legend**

- Producing or Shut In Well
- ⚡ Temp Aban Well
- ⚡ Abandoned Well
- ⚡ Dry & Aban Well
- ⊛ Earthen Pit
- Culvert
- ✱ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:  
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPANOPULOS & ASSOCIATES, INC.

**COGCC Database Information**

Status: NR Owner: PETROPLEX EQUIPMENT INC  
 T: 6S R: 62W Sec: 8 QQ: NESE 6th Meridian  
 Latitude: 39.540888 Longitude: -104.350193 NAD83

County: Elbert, CO  
 County Code: 039

**Pit Status Evaluation**

Active  Form 15: Pit Permit (1985) existing Assoc. Well Seq No(s) 06257 (6-88) PA  
 Other documentation \_\_\_\_\_  
 Aerial photo verification \_\_\_\_\_

Closed  Form 27: Remediation Workplan \_\_\_\_\_  
 Form 4: Sundry Notice \_\_\_\_\_  
 Rule 903a.(2)B \_\_\_\_\_  
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI  
 Well API Seq #(s) 06257  
 Other documentation WSIF # 436600 (6-29-88)

Abandoned  Possible un-reclaimed pit(s) or adverse conditions, no closure docs  Site Visit  
 Unknown  No Site Visit  
 Add'l Review

Notes: Common Use battery site (06284 & 06257) WSIF (1988) pits backfilled  
& site clean 06237 #8-10  
FIELD VISIT 6-4-2008: PIT BACKFILLED

**Facility ID 115109**  
Well API 05-039-06284  
Well API 05-039-06257  
Well API 05-039-06237

**Whitehead 8-15**  
Whitehead 8-15  
Whitehead 8-9  
Whitehead 8-10

**June 4, 2008**



**Photo 1. Well lease sign and steel water tank**



**Photo 2. Covered steel tank**

**Facility ID 115109**  
Well API 05-039-06284  
Well API 05-039-06257  
Well API 05-039-06237

**Whitehead 8-15**  
Whitehead 8-15  
Whitehead 8-9  
Whitehead 8-10

**June 4, 2008**




**Photo 3. Former pit site to the west of steel tanks**

**PIT STATUS EVALUATION FORM**

Facility ID: 115112

Pit Name: WHITEHEAD 31-20A

Duplicate Record(s) Pit #



**Legend**

- Producing or Shut In Well
- ♂ Temp Aban Well
- ♂ Abandoned Well
- ⊙ Dry & Aban Well
- ⊙ Earthen Pit
- Culvert
- \* Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

Feet

0 250 500 750

Image Source:  
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPANOPULOS & ASSOCIATES, INC.

**COGCC Database Information**

Status: NR Owner: SAXON OIL CO  
 T: 6S R: 62W Sec: 20 QQ: NWNE 6th Meridian  
 Latitude: 39.518777 Longitude: -104.355111 NAD83

County: Elbert, CO  
 County Code: 039

**Pit Status Evaluation**

- Active
- Form 15: Pit Permit (1976) existing Assoc. Well Seq No(s) 06150 (9-4-92) PR
- Other documentation NOAV (9-13-07)
- Aerial photo verification
- Closed
- horizontal flat tank
- Form 27: Remediation Workplan \_\_\_\_\_
- Form 4: Sundry Notice \_\_\_\_\_
- Rule 903a.(2)B
- Evidence pit(s) existed, no closure docs & well not PR, AC or SI
- Well API Seq #(s) \_\_\_\_\_
- Other documentation FIR (4-1-08) #200130071 ; FIR (11-30-07)
- Abandoned
- Possible un-reclaimed pit(s) or adverse conditions, no closure docs
- Site Visit
- No Site Visit
- Add'l Review
- Unknown

Notes: FIR (2008) "covered flat tank above ground"

FIELD VISIT 6-4-2008: PIT BACKFILLED & SITE CLEAN.

**Facility ID 115112**  
Well API 05-039-06150  
Well API 05-039-06112

**Whitehead 31-20A**  
Whitehead 31-20A  
Whitehead 31-20

**June 4, 2008**



**Photo 1. Looking east at marker for Whitehead 31-20 plugged and abandoned well; former pit site is beyond marker.**

**Facility ID 115112**  
Well API 05-039-06150  
Well API 05-039-06112

**Whitehead 31-20A**  
Whitehead 31-20A  
Whitehead 31-20

**June 4, 2008**



**Photo 2. Looking west at former pit site in foreground and Whitehead 31-20A wellhead and equipment**

PIT STATUS EVALUATION FORM

Facility ID: 115120

Pit Name: CHAMPLIN 548 "A" 1 & 2

Duplicate Record(s) Pit #



**Legend**

- Producing or Shut In Well
- ♂ Temp Aban Well
- ♂ Abandoned Well
- ⊗ Dry & Aban Well
- ☀ Earthen Pit
- Culvert
- \* Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

Feet

0 250 500 750

Image Source:  
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

**COGCC Database Information**

Status: NR Owner: SMITH ENERGY CORP  
 T: 6S R: 63W Sec: 1 QQ: SESE 6th Meridian  
 Latitude: 39.551197 Longitude: -104.387343 NAD83

County: Elbert, CO  
 County Code: 039

**Pit Status Evaluation**

Active       Form 15: Pit Permit NA      Assoc. Well Seq No(s) 06353 #1  
 Other documentation \_\_\_\_\_  
 Aerial photo verification \_\_\_\_\_

Closed       Form 27: Remediation Workplan \_\_\_\_\_  
 Form 4: Sundry Notice \_\_\_\_\_  
 Rule 903a.(2)B \_\_\_\_\_  
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI  
     Well API Seq #(s) \_\_\_\_\_  
 Other documentation FIR (1995); FIR (2004) #1230126

Abandoned       Possible un-reclaimed pit(s) or adverse conditions, no closure docs       Site Visit  
 Unknown       No Site Visit  
 Add'l Review

Notes: Common use for Champlin 548 #1 & #2  
FIR (2004) "Vault open"  
FIELD VISIT 6-4-2008: Concrete Vault. No pits at either well site.

Facility ID 115120  
Well API 05-039-06353  
Well API 05-039-06406

Champlin 548 "A" 1 & 2  
Champlin Amoco 548 A 1  
Champlin Amoco 548 A 2

June 4, 2008



Photo 1. Champlin 548 1 & 2 battery tank sign



Photo 2. Buried concrete vault

**Facility ID 115120**  
Well API 05-039-06353  
Well API 05-039-06406

**Champlin 548 "A" 1 & 2**  
Champlin Amoco 548 A 1  
Champlin Amoco 548 A 2

**June 4, 2008**



**Photo 3. Buried concrete vault and two separators to the west**