



02054360

Andrews, David

From: Andrews, David
Sent: Wednesday, June 02, 2010 12:39 PM
To: Burchett, Kirby
Cc: 'Guldan, Ryan W.'; Spector, DeAnne M.
Subject: Bentley 11-43 (PO11) CBL to Verify Cement Coverage for 05-27-2010 Cement Squeeze
Attachments: 2054335.pdf

Kirby,

A remedial cement squeeze was performed on the Bentley 11-43 (PO11) well, API No. 05-045-07910, as proposed on the attached Sundry Notice, Document No. 2054335. I understand that EnCana failed to run a cement bond log, as required by Condition of Approval (COA) No. 2 on the Sundry Notice, which states:

- 2) Verify remedial coverage with cement bond log (CBL).

Considering that EnCana has moved off location and put the well back on production, I will not require a CBL right now. However, a CBL will be required to verify the remedial cement coverage: 1) the next time a workover is required on the well, or 2) prior to plugging and abandoning the well, whichever occurs first.

Enforcement will be considered by COGCC engineering staff if EnCana fails to comply with future COA's on COGCC-approved notices of intent to perform work. Please review your internal procedures to prevent recurrence of this error.

Sincerely,

David D. Andrews, P.E., P.G.
Engineering Supervisor - Western Colorado

State of Colorado

Oil and Gas Conservation Commission

707 Wapiti Court, Suite 204

Rifle, Colorado 81650

Office Phone: (970) 625-2497 Ext. 1

Cell Phone: (970) 456-5262

Fax: (970) 625-5682

E-mail: David.Andrews@state.co.us

Website: <http://www.colorado.gov/cogcc>

CC: COGCC well file