

FORM 6

Rev 12/05

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Date Received:

Document Number:

400172408

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 100185 Contact Name: RUTHANN MORSS
Name of Operator: ENCANA OIL & GAS (USA) INC Phone: (720) 876-5060
Address: 370 17TH ST STE 1700 Fax: (720) 876-6060
City: DENVER State: CO Zip: 80202- Email: RUTHANN.MORSS@ENCANA.COM

24 hour notice required, contact: Name: BROWNING, CHUCK Tel: (970) 433-4139
Email: chuck.browning@state.co.us

API Number 05-077-09171-00 Well Name: WHITE Well Number: 14-1(A14OU)
Location: QtrQtr: NENE Section: 14 Township: 8S Range: 96W Meridian: 6
County: MESA Federal, Indian or State Lease Number:
Field Name: GRAND VALLEY Field Number: 31290

[X] Notice of Intent to Abandon [] Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.356680 Longitude: -108.069490
GPS Data:
Data of Measurement: 03/12/2007 PDOP Reading: 2.4 GPS Instrument Operator's Name: BUCK HINKSON
Reason for Abandonment: [] Dry [X] Production for Sub-economic [] Mechanical Problems
[] Other
Casing to be pulled: [] Yes [X] No Top of Casing Cement:
Fish in Hole: [] Yes [X] No If yes, explain details below
Wellbore has Uncemented Casing leaks: [] Yes [X] No If yes, explain details below
Details:

Current and Previously Abandoned Zones

Table with 7 columns: Formation, Code, Perf. Top, Perf. Bottom, Date, Method of Isolation, Plug Depth

Total: 0 zone(s)

Casing History

Table with 9 columns: Casing Type, Size of Hole, Size of Casing, Weight Per Foot, Setting Depth, Sacks Cement, Cement Bot, Cement Top, Status

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4100 with 2 sacks cmt on top. CIPB #2: Depth 1063 with 2 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 10 sks cmt from 60 ft. to 0 ft. in Plug Type: ANNULUS Plug Tagged:
Set 10 sks cmt from 60 ft. to 0 ft. in Plug Type: CASING Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:

Perforate and squeeze at 1013 ft. with 330 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Provide Technical Detail:

1. MIRU workover rig. POOH with tubing.
2. RU wireline truck. Make gauge ring run to 4150'. Set 5 1/2" CIBP @ 4100'. Pressure test casing to 500 psi.
3. Dump bail 2 sx 15.8 ppg class g cement
3. Set CIBP @ 1063' with 2 sx cement on top. Shoot 4 squeeze holes @ 1013'.
4. Establish circulation to surface with rig pump.
5. Pump 330 sx 15.8 ppg class g cement. Circulate to surface.
6. Top off production and surface casing using 60' 1-inch tubing and 15.8 ppg class g cement
7. Cut off casing 4' below ground leel and weld on 1/4" plate with weep hole.
8. Weld on marker plate with well information and back fill hole
9. Reclaim location.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: RUTHANN MORSS

Title: REGULATORY ANALYST Date: _____ Email: RUTHANN.MORSS@ENCANA.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

Attachment Check List

Att Doc Num	Name
400172424	OTHER
400172425	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)