


# COGIS - Field Inspection Report

	
API Number: <b>05-075-07181</b>	Name: <b>Schwake #A-2</b>
Location: <b>NWNE 6 11N 52W</b>	Lat: <b>40.96268</b> Long: <b>-103.21633</b>
Operator #:	Operator Name: <b>EAST CHEYENNE GAS STORAGE LLC</b>
Inspection Date: <b>8/23/2011</b>	Inspector: <b>JOHN AXELSON</b>

Inspection was: **Satisfactory**

Insp. Type: **ES**    Insp. Stat: **SI**    Reclamation (Pass, Interim or Fail):    P&A (Pass/Fail):  
 Brhd. Pressure:    Inj. Pressure:    T-C Ann. Pressure:    UIC Violation Type:  
 Violation: **N**    NOAV Sent: **N**    Date Corrective Action Due: **10/23/2011**    Date Remedied:

### Pit Inspection

Pit Type: **PW**    Oil on Pit:    Freeboard:  
 Number of Pits:    Number covered or lined: **0**    Number uncovered or unlined: **0**

Comments: **PIT CLOSURE AND REMEDIATION IN PROCESS PER APPROVED REMEDIATION #4886.**

### Field Inspection Comments and Observations

Insp. Comment	Inspection/Violation Comments
ACTION	DURING ONGOING SITE WORK, PROVIDE SIGN AT WELL HEAD IN ACCORDANCE WITH 210.B.(1). CONTINUE TO TREAT LANDFARMED MATERIAL AND REMOVE REMAINING OILY WASTE FROM FORMER BATTERY AND TREATER AREA. DOCUMENT ALL OFF SITE DISPOSAL OF OILY WASTE AND CONFIRMATION SAMPLE RESULTS FROM AREAS WHERE WASTE WAS REMOVED. VERIFY TREATMENT OF LANDFARMED MATERIAL WITH FINAL CONFIRMATION SAMPLES. DOCUMENT SURFACE RESTORATION AFTER LANDFARM HAS BEEN CLOSED AND WATER PITS HAVE BEEN BACKFILLED. ALL INFORMATION CAN BE PROVIDED AT THE CONCLUSION OF REMEDIATION IN A FINAL CLOSURE REPORT.
FENCECOMMENT	ALL FENCING RECENTLY REMOVED AS PART OF FACILITY DECOMMISSIONING.
FIREWALL	NA
GENHOUSE	GOOD - LEASE ROAD HAS RECENTLY BEEN GRADED. JUNK & TRASH FROM FACILITY DECOMMISSIONING IS STAGED IN ROLL-OFF FOR OFF SITE DISPOSAL.
MISC	INSPECTION IS RELATED TO REMEDIATION #4886 AND NOAV #200300772. PRODUCTION FACILITIES HAVE BEEN DISMANTLED AND ALL EQUIPMENT REMOVED FROM SITE. EXCAVATION OF REMAINING OILY WASTE IS PENDING. TREATMENT OF OILY WASTE FROM WATER PIT CLOSURE IS ONGOING. MATERIAL HAS BEEN AERATED RECENTLY AND STORMWATER CONTROLS ARE IN GOOD CONDITION. DISTURBED AREAS SURROUNDING LANDFARM ARE STABILIZED. CORRECTIVE ACTIONS REQUIRED BY NOAV HAVE BEEN IMPLEMENTED.
SPILCOM	OILY SOIL AT PUMPING UNIT HAS BEEN EXCAVATED AND DISPOSED OFF SITE. OILY SOIL AT FORMER TANK BATTERY AND TREATER IS STILL IN PLACE PENDING EXCAVATION AND DISPOSAL. MATERIAL

	FROM PIT CLOSURE IS STILL BEING LANDFARMED.
TANKBAT	TANK BATTERY & ASSOCIATED PRODUCTION FACILITIES RECENTLY DISMANTLED. ALL EQUIPMENT INCLUDING TANKS, TREATER, TREATER SHED, BURIED PIPES AND PUMPING UNIT WERE REMOVED FROM LOCATION.