



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Date Received:
11/09/2011

Document Number:
400222210

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.
 A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 66571 Contact Name: Joan Proulx
 Name of Operator: OXY USA WTP LP Phone: (970) 263-3641
 Address: P O BOX 27757 Fax: (970) 263-3694
 City: HOUSTON State: TX Zip: 77227 Email: joan_proulx@oxy.com

For "Intent" 24 hour notice required, Name: LONGWORTH, MIKE Tel: (970) 812-7644
COGCC contact: Email: mike.longworth@state.co.us

API Number 05-045-12221-00 Well Number: 697-15-22D
 Well Name: CASCADE CREEK
 Location: QtrQtr: SENE Section: 15 Township: 6S Range: 97W Meridian: 6
 County: GARFIELD Federal, Indian or State Lease Number: _____
 Field Name: GRAND VALLEY Field Number: 31290

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.525281 Longitude: -108.200332
 GPS Data:
 Date of Measurement: 12/29/2009 PDOP Reading: 1.6 GPS Instrument Operator's Name: BLAIR ROLLINS
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other Parasite string parted
 Casing to be pulled: Yes No Top of Casing Cement: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|-----------|-----------|-----------|----------------|---------------------|------------|
| | | | | | |

Total: 0 zone(s)

Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| CONDUCTOR | 24 | 20 | 65 | 80 | 80 | 80 | 0 | VISU |
| SURF | 14+3/4 | 9+5/8 | 36 | 2,913 | 1,609 | 2,913 | 0 | CALC |

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 30 sks cmt from 55 ft. to 0 ft. Plug Type: CASING Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

During drilling operations in 2006, the surface casing was set and the parasite string parted. No further drilling occurred. The well was temporarily abandoned with a plate welded on the surface after the well was cemented.

Procedure (attached):

Fill with fresh water to within 20' of surface.

Push cement plug to 20'.

Cement with 8.6 cu ft of Redimix to surface.

Cut off pipe within 4' of surface and weld on cover plate.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Joan Proulx

Title: Regulatory Analyst Date: 11/9/2011 Email: joan_proulx@oxy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRABACHER, JAY Date: 11/14/2011

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 5/13/2012

as per Rule 319.a, changed the surface plug from 20' length to over 50', and increased cement amount.

Attachment Check List

| <u>Att Doc Num</u> | <u>Name</u> |
|--------------------|-----------------------------|
| 2089533 | WELLBORE DIAGRAM |
| 400222210 | FORM 6 INTENT SUBMITTED |
| 400222214 | PROPOSED PLUGGING PROCEDURE |
| 400222215 | WELLBORE DIAGRAM |

Total Attach: 4 Files

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------------|--------------------------|
| Permit | Attached WBD | 11/10/2011 3:22:17 PM |
| Permit | Missing proposed WBD | 11/10/2011 1:57:38 PM |

Total: 2 comment(s)