



Looking North – east side of treater shed/battery.



Free phase hydrocarbons at base of treater and fresh dirt covering oil saturated material.



Fresh dirt covering oil saturated material NW corner tank battery.



Fresh dirt removed from berm underlain by oil saturated material NE corner battery.



Fresh dirt scraped away adjacent treater shed underlain by oil saturated material.



SS-1 Location south end of battery adjacent to treater shed from 1" to 6" bgs.



SS-2 Location center east side of battery - approximately 4" clean material.
Sample collected from 4" to 10" bgs.



SS-3 Location north end of battery – sample collected from 0” to 6” bgs.



Inside treater shed.



Ongoing leak at pumping unit.



Skim pit cover submerged and inadequate freeboard.



Oil stained dirt at production tank battery. Signs & labels inadequate.



Looking south - oily waste in east berm of water pit.