

Location ID: 334955 Williams



Viewing northerly: Rill erosion along fill slope

“PA333-33 Pad”



Viewing northerly: pipe outlet & riprap on fill slope



Viewing downslope (above). Stormwater collection drain to the right

