

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/12/2012

Document Number:

663800260

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>298715</u>	<u>335573</u>		<u>LONGWORTH, MIKE</u>

**Operator Information:**OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Friesen, Kathy	970-285-2665	Kathy.Friesen@EnCana.com	

**Compliance Summary:**QtrQtr: SWNE Sec: 29 Twp: 5S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/06/2009	200209696	OI	ND	S			N

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
274028	WELL	PR	04/12/2005	GW	045-10314	N. PARACHUTE EF07D H29 595	<input checked="" type="checkbox"/>
274029	WELL	AL	01/31/2007	LO	045-10313	N. PARACHUTE EF08D H29 595	<input checked="" type="checkbox"/>
274903	WELL	AL	01/31/2007	LO	045-13423	N. PARACHUTE EF01DH29595	<input checked="" type="checkbox"/>
274904	WELL	AL	01/31/2007	LO	045-13424	N. PARACHUTE EF02DH29595	<input checked="" type="checkbox"/>
274905	WELL	AL	06/09/2006	LO	045-13425	N. PARACHUTE EF05DH29595	<input checked="" type="checkbox"/>
274907	WELL	AL	01/31/2007	LO	045-13426	N. PARACHUTE EF09DH29595	<input checked="" type="checkbox"/>
274908	WELL	AL	01/31/2007	LO	045-13427	N. PARACHUTE EF10DH29595	<input checked="" type="checkbox"/>
278709	LEASE	PR	05/16/2005		-	N.PARACHUTE 595 07D H29	<input type="checkbox"/>
282093	WELL	PR	11/09/2006	LO	045-11655	N.PARACHUTE EF 16B G29 595	<input checked="" type="checkbox"/>
282099	WELL	PR	11/13/2006	LO	045-11653	N.PARACHUTE EF 16D G29 595	<input checked="" type="checkbox"/>
282100	WELL	PR	11/09/2006	LO	045-11652	N.PARACHUTE EF01B G29 595	<input checked="" type="checkbox"/>
282101	WELL	PR	11/13/2006	LO	045-11651	N.PARACHUTE EF09B G29 595	<input checked="" type="checkbox"/>

282108	WELL	PR	09/20/2006	GW	045-11661	N. PARACHUTE EF06D G29 595	X
282109	WELL	PR	09/21/2006	GW	045-11660	N. PARACHUTE EF07B G29 595	X
282110	WELL	PR	12/14/2005	LO	045-11659	N.PARACHUTE EF 15B G29 595	X
282111	WELL	PR	11/09/2006	LO	045-11658	N.PARACHUTE EF 15D G29 595	X
282112	WELL	PR	12/14/2005	LO	045-11657	N.PARACHUTE EF 14D G29 595	X
282113	WELL	PR	11/09/2006	LO	045-11656	N PARACHUTE EF02B-32 G29 595	X
282134	WELL	PR	08/20/2006	GW	045-11679	N.PARACHUTE EF 10B G29 595	X
282135	WELL	PR	08/23/2006	GW	045-11680	N.PARACHUTE EF11D G29 595	X
289622	WELL	PR	08/26/2008	GW	045-13844	N.PARACHUTE EF02D G29 595	X
289623	WELL	PR	08/26/2008	GW	045-13843	N.PARACHUTE EF08D G29 595	X
289624	WELL	PR	08/26/2008	GW	045-13842	N.PARACHUTE EF08B G29 595	X
289625	WELL	PR	08/10/2008	OW	045-13841	N.PARACHUTE EF03B G29 595	X
289626	WELL	PR	03/07/2007	LO	045-13840	N. PARACHUTE EF10D G29 595	X
289627	WELL	PR	02/01/2011	GW	045-13839	N.PARACHUTE EF09D G29 595	X
289628	WELL	PR	08/15/2008	OW	045-13838	N.PARACHUTE EF02B G29 595	X
291027	WELL	PR	08/26/2008	GW	045-14260	N.PARACHUTE EF 12B G29 595	X
298712	WELL	AL	08/13/2010	LO	045-17379	N. PARACHUTE EF06A-29 G29 59	X
298713	WELL	AL	08/13/2010	LO	045-17380	N. PARACHUTE EF01D-29 G29 59	X
298714	WELL	AL	08/13/2010	LO	045-17381	N. PARACHUTE EF07B-29 G29 59	X
298715	WELL	AL	08/13/2010	LO	045-17382	N. PARACHUTE EF08A-29 G29 59	X
298716	WELL	AL	08/13/2010	LO	045-17383	N. PARACHUTE EF09A-29 G29 59	X
298717	WELL	AL	08/13/2010	LO	045-17384	N. PARACHUTE EF09C-29 G29 59	X
298718	WELL	AL	08/13/2010	LO	045-17385	N. PARACHUTE EF10C-29 G29 59	X
298719	WELL	AL	08/13/2010	LO	045-17386	N. PARACHUTE EF16A-29 G29 59	X
298721	WELL	AL	08/13/2010	LO	045-17387	N. PARACHUTE EF04B-33 G29 59	X
298722	WELL	AL	08/13/2010	LO	045-17388	N. PARACHUTE EF16C-29 G29 59	X
298724	WELL	AL	08/13/2010	LO	045-17389	N. PARACHUTE EF01A-32 G29 59	X

298725	WELL	AL	08/13/2010	LO	045-17390	N. PARACHUTE EF01C-32 G29 59	X
298726	WELL	AL	08/13/2010	LO	045-17391	N. PARACHUTE EF01D-32 G29 59	X
298727	WELL	AL	08/13/2010	LO	045-17392	N. PARACHUTE EF02C-32 G29 59	X
298728	WELL	AL	08/13/2010	LO	045-17393	N. PARACHUTE EF13D-28 G29 59	X
298729	WELL	AL	08/13/2010	LO	045-17394	N. PARACHUTE EF02D-32 G29 59	X
298730	WELL	AL	08/13/2010	LO	045-17395	N. PARACHUTE EF04A-33 G29 59	X
335573	LOCATION	AC	04/14/2009		-	N. Parachute EF G29 595	
419547	WELL	XX	09/29/2010		045-19963	N. Parachute EF09C-29 G29595	X
419549	WELL	XX	09/29/2010		045-19964	N. Parachute EF01C-32 G29595	X
419550	WELL	XX	09/29/2010		045-19965	N. Parachute EF06A-29 G29595	X
419552	WELL	XX	09/29/2010		045-19966	N. Parachute EF16A-29 G29595	X
419553	WELL	XX	09/29/2010		045-19967	N. Parachute EF10B-29 G29595	X
419554	WELL	XX	09/29/2010		045-19968	N. Parachute EF13D-28 G29595	X
419555	WELL	XX	09/29/2010		045-19969	N. Parachute EF04A-33 G29595	X
419556	WELL	XX	09/29/2010		045-19970	N. Parachute EF09A-29 G29595	X
419557	WELL	XX	09/29/2010		045-19971	N. Parachute EF08A-29 G29595	X
419559	WELL	XX	09/29/2010		045-19972	N. Parachute EF02D-32 G29595	X
419560	WELL	XX	09/29/2010		045-19973	N. Parachute EF02C-32 G29595	X
419561	WELL	AL	04/12/2011		045-19974	N. Parachute EF08B-29 G29595	X
419562	WELL	XX	09/29/2010		045-19975	N. Parachute EF01D-32 G29595	X
419563	WELL	XX	09/29/2010		045-19976	N. Parachute EF04B-33 G29595	X
419564	WELL	XX	09/29/2010		045-19977	N. Parachute EF07C-29 G29595	X
419565	WELL	XX	09/29/2010		045-19978	N. Parachute EF16C-29 G29595	X
419810	WELL	PR	08/12/2011		045-20025	N. Parachute DH05-20 G29 595	X
420099	WELL	XX	10/28/2010		045-20101	N. Parachute EF02C-29 G29595	X
420136	WELL	XX	10/30/2010		045-20103	N. Parachute EF01A-32 G29595	X
420388	WELL	XX	11/13/2010		045-20145	N. Parachute DH01-31 G29 595	X
425550	PIT		09/19/2011		-	G29 WEST 595	
425551	PIT		09/19/2011		-	G29 EAST 595	

**Equipment:****Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: 40	Production Pits: 1
Condensate Tanks: _____	Water Tanks: 4	Separators: 20	Electric Motors: 4
Gas or Diesel Motors: 3	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: 3	Gas Pipeline: 1	Oil Pipeline: _____	Water Pipeline: 2
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: 2	Fuel Tanks: 1

**Location****Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Main	Satisfactory			

**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
WELLHEAD	Unsatisfactory	No sign on the DH05-20 G29	Install sign to comply with rule 210.b.	05/04/2012
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TRASH	Unsatisfactory	Rags, tumble weeds, pipe caps, pieces of plastic fencing, bottles, etc	pick up trash	05/04/2012

**Spills:**

Type	Area	Volume	Corrective action	CA Date
Lube Oil	WELLHEAD	<= 5 bbls	Clean up and remediate oil stains between DH0520 and 07D H29	05/04/2012

☒ Multiple Spills and Releases?**Equipment:**

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Bird Protectors	1	Satisfactory			
Plunger Lift	20	Satisfactory			
Horizontal Heated Separator	1	Satisfactory			
Plunger Lift	1	Satisfactory			
Gas Meter Run	9	Satisfactory			

<b>Facilities:</b>		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	400 BBLS	STEEL AST	,
S/U/V:	Satisfactory		Comment: _____	
Corrective Action:			Corrective Date: _____	
<b>Paint</b>				
Condition	Adequate			
Other (Content) _____				
Other (Capacity) _____				
Other (Type) _____				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action			Corrective Date	_____
Comment _____				
<b>Venting:</b>				
Yes/No		Comment _____		
<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 335573

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

Group	User	Comment	Date
OGLA	kubeczkod	Operator must implement best management practices to contain any unintentional release of fluids.	08/16/2010
OGLA	kubeczkod	No portion of any pit that will be used to hold liquids shall be constructed on fill material, unless the pit and fill slope are designed and certified by a professional engineer, subject to review and approval by the director prior to construction of the pit. The construction and lining of the pit shall be supervised by a professional engineer or their agent. The entire base of the pit must be in cut.	08/16/2010
OGLA	kubeczkod	The moisture content of any drill cuttings in a cuttings pit, trench, or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts. At the time of closure, the drill cuttings must also meet the applicable standards of table 910-1.	08/16/2010

Inspector Name: LONGWORTH, MIKE

OGLA	kubeczkod	Location is in a sensitive area because of shallow groundwater; therefore either a lined drilling pit or closed loop system must be implemented.	08/16/2010
OGLA	kubeczkod	Location is in a sensitive area because of shallow groundwater; therefore any pits containing fluids (if constructed) must be lined.	08/16/2010
OGLA	kubeczkod	All pits containing fluids (if constructed; reserve pit, production pit, frac pit) must be lined.	08/16/2010
OGLA	kubeczkod	Location is in a sensitive area because of proximity to surface water (East Fork Parachute Creek to the north); therefore, operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations; including, but not limited to, construction of a berm or diversion dike, diversion/collection trenches within and/or outside of berms/dikes, site grading, or other comparable measures (i.e., BMPs associated with stormwater management) sufficiently protective of the nearby surface water.	08/16/2010

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_

**Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_

**Date:** \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

## Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well				
Facility ID:	274028	API Number:	045-10314	Status: PR
Insp. Status:	PR	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	274029	API Number:	045-10313	Status: AL
Insp. Status:	AL	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	274903	API Number:	045-13423	Status: AL
Insp. Status:	AL	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	274904	API Number:	045-13424	Status: AL
Insp. Status:	AL	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	274905	API Number:	045-13425	Status: AL
Insp. Status:	AL	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	274907	API Number:	045-13426	Status: AL
Insp. Status:	AL	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	274908	API Number:	045-13427	Status: AL
Insp. Status:	AL	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	282093	API Number:	045-11655	Status: PR
Insp. Status:	PR	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	282099	API Number:	045-11653	Status: PR
Insp. Status:	PR	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	282100	API Number:	045-11652	Status: PR
Insp. Status:	PR	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	282101	API Number:	045-11651	Status: PR
Insp. Status:	PR	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	282108	API Number:	045-11661	Status: PR
Insp. Status:	PR	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	282109	API Number:	045-11660	Status: PR
Insp. Status:	PR	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	282110	API Number:	045-11659	Status: PR
Insp. Status:	PR	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	282111	API Number:	045-11658	Status: PR
Insp. Status:	PR	Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\leFormPe Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\leFormP		
Facility ID:	282112	API Number:	045-11657	Status: PR
Insp. Status:	PR			

data retrieval failed for the subreport 'Subreport0' located at: \\drdensterling\FormsR  
data retrieval failed for the subreport 'Subreport10' located at: \\drdensterling\FormsR

Date Run: 4/16/2012 Doc [#663800260] Page 8 of 12



Inspector Name: LONGWORTH, MIKE

[illegible]

Facility ID: 419554	API Number: 045-19968	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419555	API Number: 045-19969	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419556	API Number: 045-19970	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419557	API Number: 045-19971	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419559	API Number: 045-19972	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419560	API Number: 045-19973	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419561	API Number: 045-19974	Status: AL	Insp. Status: AL
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419562	API Number: 045-19975	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419563	API Number: 045-19976	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419564	API Number: 045-19977	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419565	API Number: 045-19978	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 419810	API Number: 045-20025	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 420099	API Number: 045-20101	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 420136	API Number: 045-20103	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			
Facility ID: 420388	API Number: 045-20145	Status: XX	Insp. Status: ND
Data retrieval failed for the subreport 'Subreport0' located at: \\dardenesterling\laFarmPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardenesterling\laFarmPa			

### Environmental

#### Spills/Releases:

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Comment: <input style="width: 700px;" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
<b>Water Well:</b>			
		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
<b>Field Parameters:</b>			
<input style="width: 300px;" type="text"/>			
Sample Location: <input style="width: 400px;" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

**Reclamation - Storm Water - Pit**

<b>Interim Reclamation:</b>			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: RANGELAND			
Comment: <input style="width: 750px;" type="text"/>			
1003a.	Debris removed? _____	CM _____	
	CA _____		CA Date _____
	Waste Material Onsite? _____	CM _____	
	CA _____		CA Date _____
	Unused or unneeded equipment onsite? _____	CM _____	
	CA _____		CA Date _____
	Pit, cellars, rat holes and other bores closed? _____	CM _____	
	CA _____		CA Date _____
	Guy line anchors removed? _____	CM _____	
	CA _____		CA Date _____
	Guy line anchors marked? _____	CM _____	
	CA _____		CA Date _____
1003b.	Area no longer in use? _____	Production areas stabilized ? _____	
1003c.	Compacted areas have been cross ripped? _____		
1003d.	Drilling pit closed? _____	Subsidence over on drill pit? _____	
	Cuttings management: _____		
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____		
	Production areas have been stabilized? _____	Segregated soils have been replaced? _____	
RESTORATION AND REVEGETATION			
<u>Cropland</u>			
	Top soil replaced _____	Recontoured _____	Perennial forage re-established _____

Inspector Name: LONGWORTH, MIKE

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_