

From: [Beebe, Sabre](#)
To: [Weems, Mark](#); [Nickel, Brent J](#)
Cc: [Spray, Karen](#); [Andrews, David](#); Stephen.Collins@bp.com
Subject: RE: Concerns with Braden Head Test Results
Date: Thursday, June 28, 2012 5:22:02 PM
Attachments: [2011 BH test federal Land Bank B4.pdf](#)

Mark,

I apologize for the delay in responding. I have attached the test performed on 3/8/2011. I have also contacted Brent Nickel to provide and background on work done to this well between tests or since this last test.

Sabre Beebe
Administrative Assistant for Steve Collins, Interim OSM
& Leadership Team
Office (970)- 375-7530
Cell (970)-779-9398

From: Weems, Mark [mailto:Mark.Weems@state.co.us]
Sent: Wednesday, June 27, 2012 4:25 PM
To: Beebe, Sabre
Cc: Spray, Karen; Andrews, David
Subject: Concerns with Braden Head Test Results

Hi, Sabre,

I got your name and contact information from Paul Edwards.

I have a concern about the mud or cement shooting out the surface casing as reported in the Braden head test dated 10-16-09 (see summary below). I would like to see a new or later test to see if mud or cement still shoots out as well as the results of the overall test. Based on the later or newer results, I may want to speak with a production engineer and discuss possible remedial work options.

BP
Federal Land Bank GU B #4
NESW 25 34N 9W
05-067-09687

10-16-09
Tbg=N/A Prod Csg=N/A Surf Csg=40
Surf csg bled down to a ____ in 1 minute 28 sec through a 2" pipe
Tech reports shooting grey mud or cement

Well file review

Production casing cementing reports states that the well was losing circulation at the end of the job; plug did not bump and the floats held

T/cmt @ 20' CBL

Contacted operator for review

Mark Weems, P. E.

Regional Engineer - SW Colorado

Colorado Oil and Gas Conservation Commission

50 Long Hollow Lane

Durango, CO 81301

970-259-4587 off

970-749-0624 cell