

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/14/2012

Document Number:

668500089

Overall Inspection:

Violation**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>210594</u>	<u>382862</u>		<u>Baroumand, Soraya</u>

Operator Information:OGCC Operator Number: 80530 Name of Operator: SNYDER OIL CORPAddress: 840 GESSNER STE 1400City: HOUSTON State: TX Zip: 77024**Contact Information:**

Contact Name	Phone	Email	Comment
Pavelka, Linda	(303) 228-4064	LPavelka@nobleenergyinc.com	Regulatory Analyst
ASH, MARGARET		margaret.ash@state.co.us	
RAMOS, MARTHA		martha.ramos@state.co.us	
Steve Anthony		santhony@garfield-county.com	Garfield County Vegetation Manager
Terry Porter		bill1russe@aol.com	landowner
SPRY OROURKE, LINDA		linda.spryorourk@state.co.us	
SCHOEPFLIN, SHARON		sharon.schoepflin@state.co.us	

Compliance Summary:QtrQtr: SESW Sec: 16 Twp: 6S Range: 90W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/21/2010	200316948	HR	PA	U	F	P	Y
04/21/2010	200302851	HR	PA	U	F		N

Inspector Comment:

Purpose of inspection was to investigate a complaint from the landowner that location remains unclaimed. The site visit identified a marked plugged & abandoned marker and an incomplete reclamation for the location. Rig anchors, drill pipe, scant scrap metal, rock debris, rig cable, and a 30' x 200' pit remain on location. The pit is partially vegetated but some drill cuttings and mud were visible in the eastern part of pit. The fill slopes were stable and vegetated. The cut slope was partially vegetated, but stable. Obviously, the location lacks surface grading (re-contouring). Class B noxious weeds consisting of houndstongue, musk thistle and plumeless thistle were noted at the location. There were no stormwater and erosion controls noted at the time of the inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
210594	WELL	PA	01/01/1999		045-06350	SNYDER-BARTON-PORTER 1 -16	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: Baroumand, Soraya

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 382862

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:** _____**Wildlife BMPs:****Comment:****CA:****Date:** _____**Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 210594 Type: WELL API Number: 045-06350 Status: PA Insp. Status: PA

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: Baroumand, Soraya

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Complaint:

Tracking Num	Category	Assigned To	Description	Incident Date
200353930	RECLAMATI ON	SPRY OROURKE, LINDA	<p>On June 8 a member of the Porter family, Travis, visited the COGCC Rifle office with the basic information in the email, below. Jay Krabacher recorded the following information at that time.</p> <p>Jay and Travis pulled up the three wells on COGIS and I noted that Soraya had inspected all of them.</p> <p>The API #s for these 3 are 045-06389 (Snyder-Barton Porter 1-17) 045-06388 (Snyder Barton Porter 2-21) 045-06350 (Snyder Barton Porter 1-16)</p> <p>Even though COGIS may list these as "PA" or "AL" Mr. Travis Porter claimed that the locations are not adequately nor suitably reclaimed. Snyder is operator #80530. These three still are in/on COGIS with Snyder as responsible operator.</p> <p>Jay called Noble's Regulatory Manager, Linda Pavelka, in their Denver office. Ms. Pavelka told us that, yes, Noble had taken over (bought) Snyder operations – WEST OF DIVIDE CREEK – and that DEVON ENERGY (#68355) had taken over Snyder operations EAST OF DIVIDE CREEK.</p> <p>Jay emailed Ms. Pavelka in the event anyone might wish her assistance in confirming Noble's non-involvement with this matter.</p>	06/08/2012

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Inspector Name: Baroumand, Soraya

Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed Fail No disturbance /Location never built _____

Access Roads Regraded Fail Contoured Fail Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured Fail

Compaction alleviation Fail Dust and erosion control _____

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present Fail Subsidence _____

Comment: P & A markernoted. Reclamation incomplete. Rig anchors, drill pipe, scant scrap metal, rock debris, rig cable, and a 30' x 200' pit remain on location. Noxious weeds: houndstongue, musk thistle and plumeless thistle were noted at the location.

Corrective Action: Perform Final reclamation with 1004 rules

Date **10/16/2012**

Inspector Name: Baroumand, Soraya

Overall Final Reclamation		Fail				
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
S/U/V: Satisfactory Corrective Date:						
Comment: location stable. no erosion control or stormwater issues observed at time of inspection.						
CA:						

COGCC Comments		
Comment	User	Date
Purpose of inspection was to investigate a complaint from the landowner that location remains unclaimed. The site visit identified a marked plugged & abandoned marker and an incomplete reclamation for the location. Rig anchors, drill pipe, scant scrap metal, rock debris, rig cable, and a 30' x 200' pit remain on location. The pit is partially vegetated but some drill cuttings and mud were visible in the eastern part of pit. The fill slopes were stable and vegetated. The cut slope was partially vegetated, but stable. Obviously, the location lacks surface grading (re-contouring). Class B noxious weeds consisting of houndstongue, musk thistle and plumeless thistle were noted at the location. There were no stormwater and erosion controls noted at the time of the inspection.	baroumas	07/16/2012