



Viewing northwest: drill pit conditions & contents



Viewing Southeast: drill pit, lining & fencing conditions



Appears to be Canadian Thistle. (Note infestation of Bull Thistle throughout. Both are B-List Noxious weeds



Viewing North: lease access road to location, which is a two-track primitive road.



Viewing North. D&A well marker, cellar ring, and two open boreholes, (hidden from this view). Reserve pit in background



Eastern view of D&A well marker, cellar, fencing & lumber, "debris" near the borehole entrances.



Partially caved-in (filled) rathole.



>2' dia. open borehole, estimated at approx. 20'. No groundwater or fluid was observed in the borehole @ the time of inspection.

**Morgan Creek Fee #1-43 Matagorda Production Co. API #081-07116**



Google August 2011 Aerial Photo: Site Location