

FORM

6

Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

2237498

Date Received:

08/07/2012

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 88380

Contact Name: LEE TUCKER

Name of Operator: TINDALL OPERATING COMPANY

Phone: (303) 850-7272

Address: 12741 E CALEY STE 142

Fax: (303) 850-0175

City: ENGLEWOOD State: CO Zip: 80111

Email: RLEETUCK@AOL.COM

For "Intent" 24 hour notice required,

Name: SCHURE, KYM

Tel: (970) 520-3832

COGCC contact:

Email: kym.schure@state.co.us

API Number 05-087-07611-00

Well Name: WILDCAT RANCHES

Well Number: 1

Location: QtrQtr: NESE Section: 35 Township: 6N Range: 59W Meridian: 6

County: MORGAN

Federal, Indian or State Lease Number:

Field Name: WILDCAT CREEK

Field Number: 92870

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.442100

Longitude: -103.940120

GPS Data:

Date of Measurement: 11/16/2010

PDOP Reading: 3.0

GPS Instrument Operator's Name: DARREN VEAL

Reason for Abandonment:

☐ Dry☒ Production for Sub-economic☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes☒ No

Estimated Depth: 5837

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☐ No

If yes, explain details below

Details: AS NOTED ON ATACHED COMPLETION REPORT 12/81 CEMENTED HOLES IN CASING BETWEEN 2601-2683 W/100 SXS

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
D SAND	6379	6383			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	131	120	131	0	
1ST	7+7/8	4+1/2	11.6	6,518	150	6,518	5,837	

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 30 sks cmt from 6400 ft. to 6000 ft. Plug Type: CASING Plug Tagged: ☒

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 175 ft. with 50 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at 500 ft. with 40 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at 5650 ft. with 40 sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: R. LEE TUCKER

Title: PRESIDENT Date: 8/6/2012 Email: RLEETUCK@AOL.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 8/29/2012

CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 2/27/2013

- 1) Provide 24 hour notice of MIRU to Kym Schure by e-mail at Kym.Schure@state.co.us.
- 2) D-Sand plug: (30 sx in casing at 6400'-6000'). Tag after WOC.
- 3) Niobrara plug: perf and squeeze 40 sx at 5650'. If can't pump enough rate into perfs at 5650' set 20 sx cement in casing at 2700'-2500' across 1981 squeeze cement reported.
- 4) Fox Hills plug: perf and squeeze 40 sx at 500'.
- 5) Shoe plug: perf and squeeze 50 sx at 175'. Tag plug after WOC or use a retainer. Do not use a retainer unless good returns are established first.
- 6) 15 sx at surface: Cement from 50' to surface in casing and in 4-1/2" x 8" annulus. May increase cement quantity and circulate cement to surface on shoe plug if desired.

Attachment Check List

Att Doc Num	Name
2237498	FORM 6 INTENT SUBMITTED
2237499	WELLBORE DIAGRAM
2237500	CEMENT JOB SUMMARY

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Old style completion doc #177330.	3/9/2012 1:55:22 PM

Total: 1 comment(s)