

# CAST-M CASING INSPECTION

**KINDER MORGAN**

DOE CANYON # 10

DOE CANYON

**DOLORES**

80

Elevations: K.B.: 7744.2' R.T.: 7743.2' G.L.: 7724.7'

Date Processed	11/28/2011	Logs Processed	ACE
Job Number		Date Logged	11/26/2011
Interval Processed	100'-8770'	Type Fluid In Hole	WATER
Processed By	Adam Bobay	Location	WY
Processed At	DENVER FRS		

Fold Here



Service Ticket No.:	9050472	API Serial No.:	0503361120000	PGM Version:	
DIRECTIONAL INFORMATION					
Maximum Deviation		deg. @		KOP	
Remarks:					
THANK YOU FOR CHOOSING HALLIBURTON ENEGRY SERVICES.					
*NOTE--AT THE LOG DEPTH OF 5489' THERE IS A CHANGE IN CASING WEIGHT THAT IS ABOVE THE TRANSDUCERS ABILITY AT THE LOGGED FREQUENCY TO GET AN ACCURATE READING. THE DATA MAY BE INACCURATE BELOW THIS DEPTH.					
<p>HALLIBURTON DOES NOT GUARANTEE THE ACCURACY OF ANY INTERPRETATION OF THE LOG DATA, CONVERSION OF LOG DATA TO PHYSICAL ROCK PARAMETERS OR RECOMMENDATIONS WHICH MAY BE GIVEN BY HALLIBURTON PERSONNEL OR WHICH APPEAR ON THE LOG OR IN ANY OTHER FORM. ANY USER OF SUCH DATA, INTERPRETATIONS, CONVERSIONS, OR RECOMMENDATIONS AGREES THAT HALLIBURTON IS NOT RESPONSIBLE EXCEPT WHERE DUE TO GROSS NEGLIGENCE OR WILLFUL MISCONDUCT, FOR ANY LOSS, DAMAGES, OR EXPENSES RESULTING FROM THE USE THEREOF.</p>					
HALLIBURTON					


Version No: 1 hc:3.0  
Data File: Kinder\_Morgan.cls  
Format File: M72-Fastcase.spc


## VALUATION


			INTERNAL%					
			EXTERNAL%					


ECTY	1:240 FT.	PAMP	TOTDAMG	AVRADN	PRADN	AVTHIKN	THKPN	DAMAGEP
AVTHIK			INTDAMG	MXRADN		MXTHIKN		
AVRAD			FTT	MNRADN		MNTHIKN		
			FTT					









































































































































			EXTERNAL%					
<div><div>HALLIBURTON</div><div><div>Version No:   hc:3.0</div><div>Data File: Kinder_Morgan.cls</div><div>Format File: M72-Fastcase.spc</div><div>Plot Time: 2011-11-30 15:51:57</div><div>Database Time: 14:09:35</div></div><div><div>Top Depth: 97.50</div><div>Bottom Depth: 8770.50</div></div></div>								

COMPANY	KINDER MORGAN		
WELL	DOE CANYON # 10		
FIELD	DOE CANYON		
COUNTY	DOLORES	STATE	CO
HALLIBURTON		CAST-M CASING INSPECTION	