

A flowcheck was performed, and no flow was found to be present. The well was opened and drilling was resumed.