

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
05/20/2013

Document Number:
669400673

Overall Inspection:
Unsatisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	215434	325825	LABOWSKIE, STEVE	2A Doc Num:	

Operator Information:

OGCC Operator Number: 10000 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 501 WESTLAKE PARK BLVD
 City: HOUSTON State: TX Zip: 77079

Contact Information:

Contact Name	Phone	Email	Comment
Fauth, Dan	(970) 749-4238	daniel.fauth@bp.com	Environmental Advisor (Durango)
LEONARD, MIKE		mike.leonard@state.co.us	
Floyd, Tankard	(970) 375-7572	tankard.floyd@bp.com	Environmental Advisor
Best, Julie	(970) 375-7540/ (970) 394-0131	julie.best@bp.com	Environmental Advisor

Compliance Summary:

QtrQtr: SESE Sec: 11 Twp: 34N Range: 9W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/07/2006	200103044	PR	PR	S		P	N
07/19/2005	200077098	PR	PR	S		P	N
06/24/2003	200041305	PR	PR	S		P	N
01/04/2002	200025543	PR	PR	S		P	N
01/05/2001	200015023	PR	PR	S		P	N
10/04/1999	500149096	PR	PR			P	N
10/10/1997	500149095	PR	PR			P	N
09/20/1996	500149094	PR	PR			P	N
05/02/1995	500149093	PR	PR				N
11/16/1994	500149092	PR	PR			P	N

Inspector Comment:

Inspection in response to landowner complaint (doc#200380347).

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
215434	WELL	PR	02/28/1989	GW	067-07039	HESTER GAS UNIT 1	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

--

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Other		land owner complained about weeds along access during previous growth cycle, a few immature weeds observed in places	watch for weeds this growth cycle and control	05/20/2013

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
OTHER	Satisfactory	"no chemical releases" sign		
CONTAINERS	Satisfactory	inhibitor tank		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Unsatisfactory	landowner found debris (pipe, union, gasket, wattle) in grass and placed along outside of location fence for operator to remove	remove debris	06/04/2013

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory	wood strip on east side, post and wire on others		
WELLHEAD	Satisfactory	stock panels at wellhead		
OTHER	Satisfactory	all equipment fenced with panels		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Deadman # & Marked	3	Unsatisfactory	3 anchors readily observed, at least 1 unmarked anchor inside fence, south edge of location, center	mark all anchors or remove per Rule 1003.a	07/26/2013
Gas Meter Run	1	Satisfactory			
Ancillary equipment	1	Satisfactory	telemetry		
Flow Line	1	Satisfactory			
Vertical Heated Separator	1	Satisfactory			
Ancillary equipment	1	Satisfactory	inhibitor tank at wellhead with 2ndry vessel		

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

--

Predrill

Location ID: 325825

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 215434 Type: WELL API Number: 067-07039 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Complaint

Comment: see complaint (doc # 200380347)

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: Area to south of location with poor revegetation, some gravel observed still in this area after recent re-fencing and pad size reduction.

1003a. Debris removed? Fail CM 1" pipe, hammer union, gasket, wattle
CA remove debris CA Date 06/06/2013
Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? Fail CM _____
CA mark or remove all anchors CA Date 07/29/2013

1003b. Area no longer in use? Fail Production areas stabilized ? Pass
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? Pass

Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003 f. Weeds Noxious weeds? P

Comment: good revegetation except for distinct area within straw wattle passive mitigation system. Note: some weed growth beginning but no grasses. Transmission of herbicides via stormwater is interfering with proper revegetation.

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc	Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass		Compaction	Pass	SI		
Waddles	Fail						fail for staking vertical, see BMP staking specs
Gravel	Pass		Gravel	Pass	MHSP	Pass	inhibitor tank w/ good spill prevention
Berms	Pass		Culverts	Pass			

S/U/V: Unsatisfactory Corrective Date: 06/21/2013

Comment: Well maintained graveled pad within current fence boundaries. Berm on east side of location channeling run-off to southeast corner of location and into straw wattles, wattles appear to be slowing the eastward expansion of grass kill but the kill area now appears wider in a north-south direction. No sediment erosion observed, residual herbicides are affecting stormwater which is evident by changes in vegetation off site where stormwater flows.

CA: Prevent residual herbicides from entering stormwater or prevent stormwater from leaving pad.

COGCC Comments

Comment	User	Date
Submit Form 42 with "notice of corrective actions performed" box checked when corrective actions are completed and site is ready for re-inspection.	labowsks	05/23/2013

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
669400678	close-up of grass kill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3114686
669400679	grass kill and straw wattles	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3114687
669400680	revegetation area south of pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3114688