

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
05/22/2013

Document Number:
668401331

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	<u>229324</u>	<u>314698</u>	<u>BROWNING, CHUCK</u>	2A Doc Num:	

Operator Information:

OGCC Operator Number: 16700 Name of Operator: CHEVRON PRODUCTION COMPANY
 Address: 100 CHEVRON RD
 City: RANGELY State: CO Zip: 81648

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Peterson, Diane	970-675-3842	dlpe@chevron.com	Regulatory Specialist

Compliance Summary:

QtrQtr: SWNW Sec: 23 Twp: 2N Range: 103W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/23/2012	668400518	IJ	AC	S			N
05/18/2011	200310996	RT	AC	S			N
04/13/2010	200244388	MI	AC	S			N
06/09/2009	200213871	RT	AC	S			N
05/27/2008	200198041	RT	AC	S			N
05/10/2007	200113163	RT	AC	S		P	N
05/16/2006	200093116	RT	AC	S		P	N
05/12/2005	200073300	RT	AC	U		F	Y
05/04/2004	200057682	MI	AC	S		P	N
05/13/2003	200041655	RT	AC	S		P	N
05/15/2002	200026580	RT	AC	U		F	Y
05/23/2001	200019039	RT	SI	S		P	N
05/30/2000	200009084	RT	AC	S		P	N

Inspector Comment:

Routine UIC inspection. 20 psi on casing, blowdown in 10 sec. OK

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
229324	WELL	IJ	01/01/1999	ERIW	103-06425	MCLAUGHLIN, A C 52X <input checked="" type="checkbox"/>

Equipment:

Location Inventory

--

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

The subreport 'rptInspLocInv2' could not be found

The subreport 'rptInsp3' could not be found at the s

Emergency Contact Number: (S/U/V) _____ Satisfactory _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

The subreport 'rptInsp4' could not be found at the s

The subreport 'rptInsp15' could not be found at the

The subreport 'rptInsp5' could not be found at the s

The subreport 'rptInsp6' could not be found at the s

The subreport 'rptInsp7' could not be found at the s

The subreport 'rptInsp8' could not be found at the s

The subreport 'rptInsp9' could not be found at the s

Predrill

Location ID: 314698

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 229324 Type: WELL API Number: 103-06425 Status: IJ Insp. Status: AC

The subreport 'Subreport0' could not be found at the specified location \\dndrdensterline
 The subreport 'Subreport10' could not be found at the specified location \\dndrdensterline
 The subreport 'Subreport11' could not be found at the specified location \\dndrdensterline
 The subreport 'Subreport2' could not be found at the specified location \\dndrdensterline
 The subreport 'Subreport3' could not be found at the specified location \\dndrdensterline
 The subreport 'Subreport4' could not be found at the specified location \\dndrdensterline
 The subreport 'Subreport8' could not be found at the specified location \\dndrdensterline
 The subreport 'Subreport6' could not be found at the specified location \\dndrdensterline
 The subreport 'Subreport7' could not be found at the specified location \\dndrdensterline

Inspector Name: BROWNING, CHUCK

The subreport 'rptInsp12' could not be found at the

The subreport 'rptInsp13' could not be found at the

The subreport 'rptInsp14' could not be found at the

The subreport 'Subreport10' could not be found at t