

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/12/2013

Document Number:

669600026

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	
	335429	335429	KRABACHER, JAY	2A Doc Num:	

Operator Information:OGCC Operator Number: 96850 Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVERState: COZip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
		carlos.lujan@state.co.us	
		chris.canfield@state.co.us	
jay krabacher		jay.krabacher@state.co.us	

Compliance Summary:QtrQtr: SWSE Sec: 17 Twp: 6S Range: 91W**Inspector Comment:**

Jolley – 66S91W loc # 335429 Produced Water Release Inspection # 669600026 7/11/2013, 5:15 PM: Jay Krabacher meets Karolina Blaney (WPX) at COGCC Rifle office and we drive to the location, arriving at about 5:40 PM. The information I received before going on the site investigation was that on July 2 there was a release of 50 bbls produced water, some of which ended up in a Jolley Ranch stock water pond. This area is also in a Rule 317B buffer area (Public Water System Protection) – for the town of Silt. Weather: originally blustery, overcast 90's. By 6 PM it was threatening to rain, temps in the 80's. Ms. Blaney: 48 (of 50) barrels were spread out over 11k square feet of area, averaging 2 to 3" deep contamination. About 2 bbl made it (~ ¼ - 3/8 mi) to the stock pond. WPX recovered 1 bbl of liquid. The source of the release was a poly (pipeline) riser – the sequence of wintertime/seasonal freezing/thawing had weakened it and it ruptured. This feature had been removed at the time of my visit. The water ran off, downhill, both to the north and northwest along two routes: (1) a ditch along the north edge of the road, (2) down a slight grade to the north, ending up in another ditch. These two ditches met at a culvert about 100 yards NW of the "point of impact" (POI). There was no evidence of the spill at the time of my visit – the weather has been hot and dry (until just now). The ditches were dry, as well as all other ground and areas surveyed. WPX had fenced the stock pond, adequately, and provided several portable water-tanks for the few dozen cattle grazing in the area. They plan to drain the pond (test for contamination) and refill it. WPX tested the soil in both ditches and all results are lower than the limits in COGCC Table 910-1. Ms. Blaney said that the Form 19 and other supporting documentation would be submitted to COGCC as early as July 12.6 PM, Jay Krabacher off location. (Starting to lightly rain). 15 photos on U: drive (KrabachJ : Jolley_Spill_71113

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
256113	WELL	SI	05/21/2012	GW	045-07435	JOLLEY 17-15	
295981	WELL	PR	11/07/2008	GW	045-15862	JOLLEY 17-313D	
295982	WELL	PR	11/06/2008	GW	045-15861	JOLLEY 17-315D	
297256	WELL	PR	12/03/2009	GW	045-16356	JOLLEY 17-316D	
300024	WELL	PR	04/01/2011	GW	045-17832	FEDERAL KP 44-17	
300026	WELL	PR	06/09/2011	GW	045-17833	FEDERAL KP 444-17	
300027	WELL	PR	11/30/2010	GW	045-17834	FEDERAL KP 544-17	
300028	WELL	PR	10/31/2009	GW	045-17835	FEDERAL KP 344-17	
300029	WELL	SI	05/10/2013	GW	045-17836	FEDERAL KP 543-17	
422645	PIT	CL	04/13/2011		-	KP 34-17	

Equipment:Location Inventory

Inspector Name: KRABACHER, JAY

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment
--------	---------

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
------	-----------------------------	---------	-------------------	---------

Predrill

Location ID: 335429

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____**Date:** _____**Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Environmental****Spills/Releases:**

Type of Spill: FLUID Description: produced water Estimated Spill Volume: 50

Comment: _____

Corrective Action: form 19 to be sent this week

Date: 07/13/2013

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well:			
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	Lat _____ Long _____
Field Parameters:			
Sample Location: _____			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: 07/03/2013 Date Interim Reclamation Completed: _____

Land Use: _____

Comment: affected area is pasture/grazing, culminating in stock pond. also in Town of Silt 317B area.

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: KRABACHER, JAY

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started:

Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged

Pit mouse/rat holes, cellars backfilled

Debris removed

No disturbance /Location never built

Access Roads Regraded

Contoured

Culverts removed

Gravel removed

Location and associated production facilities reclaimed

Locations, facilities, roads, recontoured

Compaction alleviation

Dust and erosion control

Non cropland: Revegetated 80%

Cropland: perennial forage

Weeds present

Subsidence

Comment:

Corrective Action:

Date

Overall Final Reclamation

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

S/U/V: Corrective Date:

Comment:

CA:

Permit:	Facility ID	Permit Num	Expiration Date
	422645	2213262	<input type="text"/>
	422645	2213262	<input type="text"/>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
669600028	stock pond	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146367
669600029	stock pond	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146368
669600030	ditch	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146369
669600031	ditch / culvert	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146370
669600032	ditch culvert	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146371
669600033	ditch	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146372
669600034	ditch	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146373
669600035	Jolley PR water spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146374
669600036	Jolley Pr water spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146376

669600037	Jolley PR water spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146377
669600038	POI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146379
669600039	POI looking east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146381
669600040	POI view to north	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146382
669600041	stock pond	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146383
669600042	stock pond	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3146384