

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax: (303)894-2109



FOR OGCC USE ONLY

RECEIVED  
10/21/2013

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

Spill report taken by:

FACILITY ID:  
335650

OPERATOR INFORMATION

Name of Operator: Encana Oil & Gas (USA), Inc.	OGCC Operator No: 100185	Phone Numbers
Address: 143 Diamond Avenue		No: 970.285.2735
City: Parachute	State: CO Zip: 81635	Fax: 970.285.2705
Contact Person: Charlie Jensen - Environmental Field Coordinator		E-Mail: charles.jensen@encana.com

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: 10/14/2013	Facility Name & No.: J25A/West Fork Water Line	County: Garfield
Type of Facility (well, tank battery, flow line, pit): pipeline		QtrQtr: NWSE Section: 25
Well Name and Number: NA		Township: 5S Range: 96W
API Number: NA		Meridian: 6th
Specify volume spilled and recovered (in bbls) for the following materials:		
Oil spilled: NA	Oil recov'd: NA	Water spilled: 3.4 bbls
		Water recov'd: 1 bbl
		Other spilled: NA
		Other recov'd: NA
Ground Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Surface Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Contained within berm? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Area and vertical extent of spill: 150' x 10'	0.5'
Current land use: range land	Weather conditions: rain and cloudy	
Soil/geology description: Nihill channery loam, 1 to 6 % slopes		
IF LESS THAN A MILE, report distance IN FEET to nearest.... Surface water: 500' wetlands: NA buildings: NA		
Livestock: NA water wells: NA Depth to shallowest ground water: 30'		
Cause of spill (e.g., equipment failure, human error, etc.): equipment failure		
Detailed description of the spill/release incident: Pipeline failure; inner liner at pipe joint was thin and pipe showed corrosion. Section of pipeline has been replaced.		

CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered):  
Lease operator noticed water flowing to surface above pipeline. Line was isolated and shut-in. No free-standing liquids to recover.

Describe any emergency pits constructed:  
NA

How was the extent of contamination determined:  
Pipeline was exposed to conduct repairs; soil samples were collected for laboratory analysis (Table 910-1 constituents).

Further remediation activities proposed (attach separate sheet if needed):  
None at this time. Awaiting laboratory results. The 3.4 bbls was based on size of hole, diameter of pipe, pressure on the line, flow rate, and estimated time of leaking.

Describe measures taken to prevent problem from reoccurring:  
The section of pipeline was replaced and relined. Lat = 39.584022, Long = -108.113181



OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response
10/14/2013	COGCC	Carlos Lujan, PH.D.	970.625.2797 ext. 7	Left message. Sent prelim Form 19 on 10/15/2013.
10/14/2013	Garfield County	Kirby Wynn	970.625.5905	Left message. Copied prelim Form 19 on 10/15/2013.

Spill/Release Tracking No: 2146741





Revised: 11/12/2012