

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
11/25/2013

Document Number:
673700060

Overall Inspection:
Unsatisfactory

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|-----------------------|--------------------|--------------------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | <input type="checkbox"/> |
| | <u>297958</u> | <u>309647</u> | <u>Sherman, Susan</u> | 2A Doc Num: | |

Operator Information:

OGCC Operator Number: _____

Name of Operator: RUNNING FOXES PETROLEUM INC

Address: 6855 S. HAVANA ST #400

City: CENTENNIAL State: CO Zip: 80112

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-----------------------|---------|
| NOTO, JOHN | | john.noto@state.co.us | |
| KEPPEL, KENT | | kkeppel@atoka.com | |

Compliance Summary:

QtrQtr: SESE Sec: 1 Twp: 13S Range: 56W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 08/21/2013 | 668601283 | PA | PA | Satisfactory | | I | No |
| 12/18/2012 | 668200369 | PA | PA | Unsatisfactory | | Fail | No |
| 04/06/2012 | 664000460 | PA | PA | Unsatisfactory | | Fail | No |
| 01/26/2012 | 664000336 | PA | PA | Unsatisfactory | | Fail | No |
| 06/14/2011 | 200313017 | CO | PA | Unsatisfactory | F | Fail | Yes |
| 05/10/2011 | 200310628 | SR | PA | Unsatisfactory | F | Fail | Yes |
| 01/27/2011 | 200293323 | SR | PA | Unsatisfactory | | | Yes |
| 01/27/2011 | 200293321 | CA | PA | Satisfactory | | | No |
| 01/05/2011 | 200292599 | CO | TA | Unsatisfactory | | | Yes |
| 07/07/2010 | 200264702 | SR | TA | Unsatisfactory | I | | Yes |
| 02/22/2010 | 200232145 | PR | WO | Unsatisfactory | | | Yes |
| 12/03/2009 | 200223543 | PR | WO | Unsatisfactory | | | No |

Inspector Comment:

EXISTING NEARBY DISTURBED AREAS TO THE NE OF THE LOCATION WERE REVIEWED ON THE 1990 AND 2011 AERIAL MAPS. BECAUSE THE SPUD DATE FOR THE WELL WAS 2008, THE DISTURBED AREAS ARE LIKELY ASSOCIATED WITH AGRICULTURE AND NOT OIL AND GAS RELATED.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|--|
| 297958 | WELL | PA | 01/27/2011 | OW | 073-06349 | JOLLY RANCH 16C-1 | PA <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

Inspector Name: Sherman, Susan

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| | |

| Flaring: | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 297958

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 297958 Type: WELL API Number: 073-06349 Status: PA Insp. Status: PA

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: _____

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland
 Top soil replaced _____ Recontoured _____ Perennial forage re-established _____
Non-Cropland
 Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____
Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: **BOND RELEASE REQUEST 08/29/2012. BARE SPOTS EVIDENT. ROAD NEEDS TO BE RIPPED**

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present Pass Subsidence _____

Comment: **VEGETATION SPARSE. LAST INSPECTION ON 8/21/2013 REQUESTED WEED CONTROL AND SEEDING AS NEEDED BY 11/21/2013. EVIDENCE OF WEED CONTROL. (SEE ATTACHED PHOTOS)**

Corrective Action: _____ Date _____

Overall Final Reclamation In Process Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 673700101 | JOLLY RANCH 16C_1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236706 |
| 673700102 | JOLLY RANCH 16C_1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236707 |
| 673700103 | JOLLY RANCH 16C_1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236708 |
| 673700104 | JOLLY RANCH 16C_1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236709 |
| 673700105 | JOLLY RANCH 16C_1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3236710 |