

FORM
19
Rev 6/99

State of Colorado
Oil and Gas Conservation Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303)894-2100 Fax:(303)894-2109

FOR OGCC USE ONLY

RECEIVED
11/16/2011

Spill report taken by:

FACILITY ID:

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation

OPERATOR INFORMATION

Name of Operator: <u>Chevron Production</u>	OGCC Operator No: <u>16700</u>	Phone Numbers
Address: <u>100 Chevron Road</u>		No: <u>970-675-3705</u>
City: <u>Rangely</u> State: <u>CO</u> Zip: <u>81648</u>		Fax: <u>970-675-3809</u>
Contact Person: <u>E. Faithe Schwartzengraber - HE Specialist Environmental</u>		Email: <u>efsc@chevron.com</u>

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: <u>14-Nov-11</u>	Facility Name & No: <u>Rangely Weber Sand Unit</u>	County: <u>Rio Blanco</u>
Type of Facility (well, tank battery, flow line, pit): <u>Injection System / Injection Line</u>		QtrQtr: <u>SWNW</u> Section: <u>23</u>
Well Name and Number: <u>AC McLaughlin 52X</u>		Township: <u>2N</u> Range: <u>103W</u>
API Number: <u>05-103-0642500</u>		Meridian: <u>6PM</u>
Specify volume spilled and recovered (in bbls) for the following materials:		
Oil spilled: <u>0</u>	Oil recov'd: <u>0</u>	Water spilled: <u>159.15 bbl</u> Water recov'd: <u>148.10 bbl</u> Other spilled: <u>0</u> Other recov'd: <u>0</u>
Ground Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Surface Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Contained within berm? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Area and vertical extent of spill: <u>2610 X 159 feet</u>	
Current land use: <u>Non Crop Land</u>	Weather conditions: <u>55 Degrees F and Sunny</u>	
Soil/geology description: <u>Silty Clay</u>		
IF LESS THAN A MILE, report distance IN FEET to nearest ... Surface water: <u>N/A</u> wetlands: <u>N/A</u> buildings: <u>N/A</u>		
Livestock: <u>N/A</u> Water wells: <u>N/A</u> Depth to shallowest ground water: <u>N/A</u>		
Cause of spill (e.g. equipment failure, human error, etc.): <u>Threads separated from the line.</u> Detailed description of the spill/release incident:		
<u>A leak occurred on a three inch fiberglass pipe approximately 200 feet East of AC McLaughlin 52X. Approximately 159.15 bbls of brine water and 0 bbls of crude oil were released.</u>		

CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered): The line was shut in immediately upon detection. Vacuum trucks removed all of the free fluid, estimated recovery is approximately 148.10 bbls of brine water and 0 bbls of crude oil. The fluids that were picked up, were taken to the truck unloading facility at the Main Water Plant for recycling.

Describe any emergency pits constructed: A dike was constructed across the flow path.

How was the extent of contamination determined?
Visual Inspection. Chevron MCA Spill Calculation Worksheet.

Further remediation activities proposed (attach separate sheet if needed):

Describe measures taken to prevent problem from reoccurring: Line will be repaired and returned to service.



OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response
11/15/11	COGCC	Chris Canfield	970-625-2497	Left Voice Message at 10:40am
11/15/2011	BLM	Bill Kraft	970-878-3817	Left Voice Message at 10:45am

Spill/Release Tracking No: 2221266

Chevron-AC McLaughlin 52X



Chevron –AC McLaughlin 52X

