

FORM
19
Rev 6/99

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303)894-2100 Fax: (303)894-2109



FOR OGCC USE ONLY

RECEIVED
2/25/2014

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation

Spill report taken by:

FACILITY ID:
315589

OPERATOR INFORMATION

Name of Operator: Chevron Production	OGCC Operator No: 16700	Phone Numbers
Address: 100 Chevron Road		No: 970-675-3705
City: Rangely	State: CO Zip: 81648	Fax: 970-675-3809
Contact Person: Tammie Lee Crossen - HE Specialist		Email: tvzf@chevron.com

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: 2/18/2014	Facility Name & No: Rangely Weber Sand Unit	County: Rio Blanco
Type of Facility (well, tank battery, flow line, pit): Production Flow Line		QtrQtr: NWNW Section: 36
Well Name and Number: Emerald 80X		Township: 2N Range: 103W
API Number: 05-103-08769		Meridian: 6PM

Specify volume spilled and recovered (in bbls) for the following materials:

Oil spilled: 0.3	Oil recov'd: 0.3	Water spilled: 11	Water recov'd: 10.5	Other spilled: 0	Other recov'd: 0
------------------	------------------	-------------------	---------------------	------------------	------------------

Ground Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Surface Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Contained within berm? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Area and vertical extent of spill: 1' X 2000'

Current land use: Non Crop Land Weather conditions: 25 Degrees Sunny

Soil/geology description: Silty Clay

IF LESS THAN A MILE, report distance IN FEET to nearest ... Surface water: 3,751 wetlands: 3,730 buildings: None

Livestock: None Water wells: 3,330 Depth to shallowest ground water: 4335

Cause of spill (e.g. equipment failure, human error, etc.): 4" Fiberglass Pipe Failure Detailed description of the spill/release incident:

A leak occurred on a four inch fiberglass production flow line at Emerald 80X which was shut in for sub-surface maintenance.

CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered): The line was shut in immediately upon detection. Vacuum trucks removed all of the free fluid. The fluids that were picked up were taken to the truck unloading facility at the Main Water Plant for recycling. All contaminated soils were taken to the landfarm for remediation.

Describe any emergency pits constructed: NA

How was the extent of contamination determined?
Visual Inspection. Chevron MCA Spill Calculation Worksheet.

Further remediation activities proposed (attach separate sheet if needed):
Effected area was fresh water washed and soil samples will be taken.

Describe measures taken to prevent problem from reoccurring: This section of pipe will totally be replaced and returned to service.


OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response
2/18/2014	COGCC	Kris Neidel	(970) 871-1963	LVM at 1725
2/18/2014	Rio Blanco County	Mark Sprague	(970) 878-9584	Email sent at 1730
2/18/2014	Chevron Land Man	Scott Ritter	1-432-687-7754	Email sent at 1728

Spill/Release Tracking No: 2147813

Chevron – Emerald 80X



WELL HEAD



SPILL LOCATION



PERENNIAL STREAM



BLM Land



Chevron – Emerald 80X

